



report date: 2024-03-28

General information

|                     |                        |
|---------------------|------------------------|
| Make                | BMW                    |
| Model               | 525 525D SPORT TOURING |
| Colour              | Grey                   |
| Year of manufacture | 2005                   |
| Top speed           | 139 mph                |
| 0 - 60 mph          | 8.5 seconds            |
| Gearbox             | 6 speed automatic      |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 177 BHP             |
| Max. torque             | 400 Nm at 2.000 rpm |
| Engine capacity         | 2.497 cc            |
| Cylinders               | 6                   |
| Fuel type               | Diesel              |
| Consumption city        | 25.9 mpg            |
| Consumption extra urban | 43.5 mpg            |
| Consumption combined    | 35.3 mpg            |
| CO2 emission            | 213 g/km            |
| CO2 label               | K                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-11-03                  |
| Pictures      | 14                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-12-28 |
| MOT pass rate      | 89 %       |
| MOT passed         | 16         |
| Failed MOT tests   | 2          |
| Total advice items | 39         |
| Total items failed | 3          |

MOT #182023-12-22 14:33

MOT test number121600485573

Result✓ Passed

Next expiry date2024-12-28

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Handbrake has very little reserve travel
- Minor** Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning high level brake light (4.3.1 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Both headlamps have poor beam images
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #17**

2023-12-19 16:25

**MOT test number**

890534000445

**Result****✗ Failed**

**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt rear arm (5.3.4 (b) (ii))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Handbrake has very little reserve travel

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice** Both headlamps have poor beam images

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**Fail** Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

**Minor** Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning high level brake light (4.3.1 (a) (i))

**MOT #16** 2022-12-23 11:02**MOT test number** 107588082797**Result** ✓ Passed**Advice** Front Headlamp has a product on the lens but not seriously reducing light output nearside and offside (4.1.4 (b))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Hand break lever high little reserve travel left**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))**MOT #15** 2021-12-23 16:45**MOT test number** 251345647456**Result** ✓ Passed**MOT #14** 2020-12-19 12:48**MOT test number** 182040389317**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #13** 2019-11-30 12:01**MOT test number** 697997315200**Result** ✓ Passed**MOT #12** 2018-12-08 12:52**MOT test number** 168484862795**Result** ✓ Passed

**MOT #11** 2017-12-16 09:13**MOT test number** 139858812148**Result** ✓ Passed**MOT #10** 2016-12-03 08:31**MOT test number** 172238856316**Result** ✓ Passed**MOT #9** 2015-12-24 12:39**MOT test number** 438248622391**Result** ✓ Passed**MOT #8** 2014-12-05 12:38**MOT test number** 499689234417**Result** ✓ Passed**Notice** Floor covers front to rear of vehicle**MOT #7** 2013-12-11 15:34**MOT test number** 475315643411**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-12-04 09:15**MOT test number** 547319932357**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2011-12-29 15:01**MOT test number** 937763761395**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2011-12-29 11:28**MOT test number** 489113761374**Result** ✗ Failed**Notice** Small cuts in o/s front tyre inner sidewall**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-12-10 10:56**MOT test number** 653314040301**Result** ✓ Passed**MOT #2** 2009-12-15 10:43**MOT test number** 412369549489**Result** ✓ Passed**MOT #1** 2008-12-10 11:50**MOT test number** 793525248339**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
28 December 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 March             |
| <b>Days left</b>        | 306                             |
| <b>MOT expiry date</b>  | 28 December 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | K          |
| <b>Single payment (12 months)</b>              | £ 395,00,- |
| <b>Single six month payment</b>                | £ 217,25,- |
| <b>Total payable by 12 monthly instalments</b> | £ 414,75,- |





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this BMW had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 1   |
| Current registration |   |
| Plate since          | 2024-03-28  |
| Current registration |   |
| Plate since          | 2024-03-28  |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 20                       |
| First mileage registration | 2005-12-16               |
| Last registration          | 2023-12-22               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2005-12-16 | 6 mi       |
| Registration #2  | 2008-12-10 | 75.726 mi  |
| Registration #3  | 2009-12-15 | 89.167 mi  |
| Registration #4  | 2010-12-10 | 101.064 mi |
| Registration #5  | 2011-12-29 | 112.321 mi |
| Registration #6  | 2011-12-29 | 112.330 mi |
| Registration #7  | 2012-12-04 | 117.912 mi |
| Registration #8  | 2013-12-11 | 122.502 mi |
| Registration #9  | 2014-12-05 | 126.346 mi |
| Registration #10 | 2015-12-24 | 132.886 mi |
| Registration #11 | 2016-12-29 | 135.337 mi |
| Registration #12 | 2017-12-29 | 135.337 mi |
| Registration #13 | 2018-12-29 | 135.337 mi |
| Registration #14 | 2019-12-29 | 135.337 mi |
| Registration #15 | 2020-12-29 | 135.337 mi |
| Registration #16 | 2021-12-29 | 135.337 mi |
| Registration #17 | 2022-12-29 | 135.337 mi |
| Registration #18 | 2023-12-22 | 135.337 mi |
| Registration #19 | 2023-12-22 | 135.337 mi |
| Registration #20 | 2023-12-22 | 135.337 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1846 mm |
| Height              | 1491 mm |
| Length              | 4843 mm |
| Wheel base          | 2886 mm |
| Max. allowed weight | 2285 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |

**Engine number**

26306077