




report date: 2024-03-28

General information

Make	VOLVO
Model	V50 SE V50
Colour	Blue
Year of manufacture	2004
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	170 BHP
Max. torque	225 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.4 mpg
Consumption extra urban	42.2 mpg
Consumption combined	31.0 mpg
CO2 emission	220 g/km
CO2 label	K





MOT history

MOT expiry date	2020-11-17
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	15
Total items failed	7

MOT #17	2019-05-14 11:03
MOT test number	788055049255
Result	✓ Passed
Next expiry date	2020-11-17

MOT #16	2019-05-14 09:09
MOT test number	841614687555
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn bush (5.3.4 (a) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2018-05-09 11:15
MOT test number	271619836254
Result	✓ Passed
Advice	Engine management light is

**MOT #14** 2017-05-16 14:10**MOT test number** 645170003091**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement BOTH FRONTS (2.4.G.2)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #13** 2017-05-16 09:13**MOT test number** 919475944109**Result** ✗ Failed**Fail** Tyre tread depth below requirements of 1.6mm BOTH FRONTS (4.1.E.1)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement BOTH FRONTS (2.4.G.2)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #12** 2016-05-12 11:19**MOT test number** 330065352856**Result** ✓ Passed**Advice** Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** 2 child seats fitted**MOT #11** 2015-05-18 12:36**MOT test number** 395748835141**Result** ✓ Passed

**MOT #10** 2015-05-15 11:38**MOT test number** 345345535160**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-05-13 10:52**MOT test number** 189653834119**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-05-14 11:21**MOT test number** 278084833164**Result** ✓ Passed**MOT #7** 2012-05-16 17:29**MOT test number** 128927832143**Result** ✓ Passed**MOT #6** 2011-07-05 13:09**MOT test number** 295006281496**Result** ✓ Passed**MOT #5** 2010-10-05 12:07**MOT test number** 462828170268**Result** ✓ Passed

**MOT #4** 2010-07-08 10:45**MOT test number** 903019880192**Result** ✓ Passed**Advice**

Nearside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance
(1.1.A.3d)

MOT #3 2009-07-17 15:48**MOT test number** 193878699178**Result** ✓ Passed**Notice**

N/s & o/s front brake pads worn low advise replacement soon.

MOT #2 2008-08-06 13:39**MOT test number** 921729018270**Result** ✓ Passed**MOT #1** 2007-08-23 09:01**MOT test number** 680155137255**Result** ✓ Passed**Notice**

Offside front and nearside front inner and outer brake pads wearing low



Tax & MOT check

✕
Untaxed

Tax expired:
31 October 2020

✕
MOT

Expired:
17 November 2020

Tax status	Expired at 31 October 2020
Days left	1276 days too late
MOT expiry date	17 November 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2004-09-03
Last registration	2019-05-14
Complete history	See info



Registration #1	2004-09-03	23 mi
Registration #2	2007-08-23	32.590 mi
Registration #3	2008-08-06	44.470 mi
Registration #4	2009-07-17	57.707 mi
Registration #5	2010-07-08	67.599 mi
Registration #6	2010-10-05	69.141 mi
Registration #7	2012-05-16	78.457 mi
Registration #8	2013-05-14	84.500 mi
Registration #9	2014-05-13	90.827 mi
Registration #10	2015-05-20	95.377 mi
Registration #11	2016-05-20	95.377 mi
Registration #12	2017-05-20	95.377 mi
Registration #13	2018-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2020-05-20	95.377 mi
Registration #16	2021-05-20	95.377 mi
Registration #17	2022-05-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	3395899