





report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Black
Year of manufacture	2009
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	225 g/km
CO2 label	K



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 3

Date 2022-01-25

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-10-14	
-----------------	--

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

Entry 1

Date	2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2023-03-30
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	20
Total items failed	29

MOT #14	2022-03-08 11:12
MOT test number	556017044394
Result	✓ Passed
Next expiry date	2023-03-30
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #13		2022-03-07 16:23
MOT test number		458703681224
Result		X Failed
Fail Offside Front Wi	ndscreen wiper does not clear the windscree	en effectively (3.4 (b) (ii))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Nearside Rea	ar Tyre slightly damaged/cracking or perishin	ng (5.2.3 (d) (ii))

MOT #12	2021-03-31 14:5
MOT test	number 12302528116
Result	✓ Passe
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))

CarCheck.co.uk page 3/14




report date: 2024-03-28

MOT test number

Result

Advice Front Brake disc worn, but not excessively x2 (1.1.14 (a) (i))

Rear Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))



CarCheck.co.uk page 4/14



DAO9SKU

report date: 2024-03-28

MOT #9 2020-02-14 14:43

MOT test number 183451860404 Result × Failed Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) **Advice** Run flat warning on dash Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Nearside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i)) Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Nearside Parking brake inoperative on one side (1.4.1 (a)) **Advice** Brake pad warning on dash Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c)) **Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) **Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Offside Rear Road wheel fixing missing (5.2.1 (a) (i)) Fail

Advice Rear brake pads getting low

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number

Result

Advice
Offside Brake pipe slightly corroded front to rear (3.6.B.2c)

Advice
Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #7 2017-09-06 08:32 **MOT** test number 983128880665 Result × Failed Fail Nearside Front Wheel bolt(s) missing (4.2.A.1e) Fail Nearside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) Fail Windscreen washer provides insufficient washer liquid (8.2.3) **Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c) Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2) **Fail** Nearside Headlamp not working on dipped beam (1.7.5a) Advice Nearside Brake pipe slightly corroded front to rear (3.6.B.2c)

MOT #6

MOT test number

485816468068

Result

Advice
(2.4.G.2)

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

MOT #5

MOT test number

909044904986

Result

Pass with rectification

Exhaust has a major leak of exhaust gases (7.1.2)

Advice
(2.4.G.2)

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #4	2015-10-21 13:39
MOT test number	599862291430
Result	✓ Passed

Result		✓ Passed
MOT #	3	2015-10-19 15:51
MOT te	est number	877331708271
Result		× Failed
Fail	Nearside Front suspension has excessive play in a lower suspension ball joint (2.	5.B.1a)
Fail	Offside Front Tyre(s) incorrect because a lightweight or space saving wheel is fit	ted (4.1.A.1b)
Fail	Offside Front suspension has excessive play in a lower suspension ball joint (2.5.	B.1a)

MOT #2	2014-07-01 12:51
MOT test number	879412684106
Result	✓ Passed
MOT #1	2012-07-02 11:33
MOT test number	176914182188
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax expired: 30 September 2022

X MOT

Expired: 30 March 2023

Tax status	Expired at 30 September
Days left	576 days too late
MOT expiry date	30 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14




report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



DA09SKU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-26
Last registration	2022-03-08
Complete history	See info



Registration #1	2009-06-26	27 mi
Registration #2	2012-07-02	42.465 mi
Registration #3	2014-07-01	69.256 mi
Registration #4	2015-10-19	79.751 mi
Registration #5	2015-10-21	79.752 mi
Registration #6	2016-09-09	85.932 mi
Registration #7	2016-09-09	85.932 mi
Registration #8	2017-09-06	92.777 mi
Registration #9	2017-09-06	92.777 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040802276

CarCheck.co.uk page 14/14