





report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC
Colour	Red
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-08

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-25
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	16
Total items failed	3

MOT #17	2024-01-02 12:13
MOT test number	460996695107
Result	✓ Passed
Next expiry date	2025-01-25

MOT #16		2023-01-03 12:15
MOT test	number	464638393842
Result		✓ Passed
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice (a) (ii))	Front Inner Brake disc worn, pitted or scored, but not seriously weakened Slight	corrosion (1.1.14

MOT #15		2023-01-03 12:15
MOT test	number	660644969507
Result		X Failed
Pass wit	th rectification Headlamp aim too low (4.1.2 (a))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened Slight corrosion (1.1.14 (a) (ii))		Slight corrosion (1.1.14
Advice	Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a	a) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #14 2022-01-26 17:53

MOT test number 122330138032

MOT #13 2022-01-24 17:43

MOT test number 601741155572

Result X Failed

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12 2021-05-20 10:20

MOT test number 771380869029

Result
✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2020-07-01 10:53

MOT test number 849210887160

Result \rightarrow Passed

MOT #10 2019-03-25 14:07

MOT test number 540265452511

Result
✓ Passed

MOT #9 2018-04-06 11:07

MOT test number 921169977708

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8

MOT test number

709785508553

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7

MOT test number

Result

MOT #6

MOT test number

2015-04-16 11:50

MOT test number

285546305413

Result

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT test number

Fass with rectification

Rear Stop lamp not working (1.2.1b)

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #4

MOT test number

616053914180

Result

Vehicle's internal headlight adjuster altered to recheck lights

2014-04-23 12:31

√ Passed

MOT #3

MOT test number

945694413133

Result

✓ Passed

CarCheck.co.uk page 5/13



Pass with rectification

BG10VAX

report date: 2024-03-29

 MOT #2
 2013-03-26 11:46

 MOT test number
 279875883070

 Result
 ✓ Passed

 MOT #1
 2013-03-26 11:46

 MOT test number
 417275083005

 Result
 X Failed

Offside Rear Registration plate lamp not working (1.1.C.1d)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-18
Last registration	2024-01-02
Complete history	See info



Registration #1	2010-05-18	26 mi
Registration #2	2013-03-26	28.541 mi
Registration #3	2013-04-24	28.868 mi
Registration #4	2014-04-23	33.335 mi
Registration #5	2015-04-16	37.925 mi
Registration #6	2016-04-12	42.613 mi
Registration #7	2017-04-04	46.614 mi
Registration #8	2018-04-06	49.654 mi
Registration #9	2019-03-25	53.471 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		D.277 es

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13