



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ZEST 3
Colour	Silver
Year of manufacture	2005
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.800 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-13
Pictures	7
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-17
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	17
Total items failed	8

MOT #20	2023-09-18 12:20
MOT test number	219553386172
Result	✓ Passed
Next expiry date	2024-09-17

MOT #19	2023-09-18 12:20
MOT test number	240134988623
Result	✗ Failed
Pass with rectification	Rear Tyre tread depth below requirements of 1.6mm both side (5.2.3 (e))

MOT #18	2022-08-25 16:59
MOT test number	172006146076
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2021-09-10 10:55**MOT test number** 609406736951**Result** ✓ Passed**MOT #16** 2021-09-06 15:50**MOT test number** 807807612405**Result** ✗ Failed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Position lamp slightly affected by the operation of another lamp both sides (4.2.3 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2020-01-17 12:10**MOT test number** 693934808789**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-01-22 15:28**MOT test number** 441767203682**Result** ✓ Passed

**MOT #13** 2019-01-22 13:51**MOT test number** 698805478009**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))**MOT #12** 2018-01-22 11:05**MOT test number** 433718524591**Result** ✓ Passed**MOT #11** 2017-03-13 09:09**MOT test number** 893148455429**Result** ✓ Passed**MOT #10** 2016-03-12 10:26**MOT test number** 791695368947**Result** ✓ Passed**MOT #9** 2015-03-13 10:46**MOT test number** 218552475056**Result** ✓ Passed**MOT #8** 2014-03-20 08:50**MOT test number** 235129774046**Result** ✓ Passed**MOT #7** 2014-03-20 08:50**MOT test number** 449959274089**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**MOT #6** 2013-03-18 11:35**MOT test number** 636637173022**Result** ✓ Passed**MOT #5** 2012-03-21 12:42**MOT test number** 235371282027**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-24 10:52**MOT test number** 945563181095**Result** ✓ Passed**Notice** Slight play in offside front track rod end**MOT #3** 2010-03-18 17:25**MOT test number** 193387970061**Result** ✓ Passed**MOT #2** 2009-03-24 10:14**MOT test number** 641193289083**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Steering arm has slight play**Notice** Front wipers starting to smear**MOT #1** 2008-03-26 13:53**MOT test number** 120296788441**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>LR05PFO</b>
Plate since	2024-03-29
Current registration	<b>LR05PFO</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-30
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2005-03-30	28 mi
Registration #2	2008-03-26	23.614 mi
Registration #3	2009-03-24	30.387 mi
Registration #4	2010-03-18	39.071 mi
Registration #5	2011-03-24	50.484 mi
Registration #6	2012-03-21	58.414 mi
Registration #7	2013-03-18	65.717 mi
Registration #8	2014-03-20	73.160 mi
Registration #9	2015-03-13	76.751 mi
Registration #10	2016-03-12	82.317 mi
Registration #11	2017-03-13	84.516 mi
Registration #12	2018-03-20	85.337 mi
Registration #13	2019-03-20	85.337 mi
Registration #14	2020-03-20	85.337 mi
Registration #15	2021-03-20	85.337 mi
Registration #16	2022-03-20	85.337 mi
Registration #17	2023-03-20	85.337 mi
Registration #18	2024-03-20	85.337 mi
Registration #19	2025-03-20	85.337 mi
Registration #20	2026-03-20	85.337 mi
Registration #21	2027-03-20	85.337 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FP7N4789506