



RA07UEB

report date: 2024-03-28

General information

Make	MAZDA
Model	3 D TS
Colour	Blue
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	245 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	128 g/km
CO2 label	D





MOT history

MOT expiry date	2021-01-15
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	23
Total items failed	10

MOT #14	2019-07-16 16:36
MOT test number	412521945096
Result	✓ Passed
Next expiry date	2021-01-15
Advice	Central Front Exhaust has a minor leak of exhaust gases at turbo (6.1.2 (a))

MOT #13	2019-07-15 10:53
MOT test number	777562897530
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Central Front Exhaust has a minor leak of exhaust gases at turbo (6.1.2 (a))

MOT #12	2018-06-11 09:49
MOT test number	105643993051
Result	✓ Passed

**MOT #11**

2017-07-05 15:28

MOT test number

759353628659

Result

✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower arm rear bush (2.4.G.2)**Advice** E.M.L. (engine management light) on**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #10**

2017-07-05 09:04

MOT test number

223331331180

Result

✗ Failed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement lower arm rear bush (2.4.G.2)**Advice** E.M.L. (engine management light) on**Fail** Nearside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement lower arm rear bush (2.4.G.2)**MOT #9**

2016-06-28 15:09

MOT test number

653142994371

Result

✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2016-06-28 08:50**MOT test number** 804900472464**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Eml on**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2015-06-30 12:03**MOT test number** 768661385187**Result** ✓ Passed**MOT #6** 2014-06-24 16:01**MOT test number** 915565474112**Result** ✓ Passed**Notice** Oil leak**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-06-20 15:51**MOT test number** 646551773198**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2012-07-06 10:52**MOT test number** 379628082113**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2011-06-17 14:32**MOT test number** 457378861131**Result** ✓ Passed**MOT #2** 2011-06-17 12:59**MOT test number** 209858961473**Result** ✗ Failed**Fail** Offside Front position lamp(s) incorrect colour (1.1.A.3e)**Fail** Offside Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**Fail** Nearside Front position lamp(s) incorrect colour (1.1.A.3e)**Fail** Nearside Front position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)**MOT #1** 2010-06-16 13:53**MOT test number** 281747560110**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
22 December 2020

✕
MOT

Expired:
15 January 2021

Tax status	Expired at 22 December 2020
Days left	1223 days too late
MOT expiry date	15 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-06-18
Last registration	2019-07-16
Complete history	See info



Registration #1	2007-06-18	15 mi
Registration #2	2010-06-16	18.355 mi
Registration #3	2011-06-17	33.457 mi
Registration #4	2011-06-17	33.457 mi
Registration #5	2012-07-06	51.442 mi
Registration #6	2013-06-20	59.330 mi
Registration #7	2014-06-24	66.724 mi
Registration #8	2015-06-30	73.999 mi
Registration #9	2016-06-30	81.274 mi
Registration #10	2017-06-30	88.549 mi
Registration #11	2018-06-30	95.824 mi
Registration #12	2019-06-30	103.099 mi
Registration #13	2020-06-30	110.374 mi
Registration #14	2021-06-30	117.649 mi
Registration #15	2022-06-30	124.924 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Kerb weight	1331 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Y6 263683