



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER LM35 BUSINESS DCI S/R P/V
Colour	White
Year of manufacture	2016
Top speed	89 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.500 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	36.2 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 3


Date	2022-05-04
Pictures	20
Listing price	View report



source: cargurus.co.uk

Entry 2


Date	2022-03-05
Pictures	19
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-12-24
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-01
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	19
Total items failed	18

MOT #8	2023-05-22 10:33
MOT test number	436108504991
Result	✓ Passed
Next expiry date	2024-06-01
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #7	2022-05-20 07:45
MOT test number	364821004677
Result	✓ Passed

MOT #6	2022-05-19 06:16
MOT test number	299787681069
Result	✗ Failed
Fail	All outline marker lamps not working (4.2.1 (a) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #5	2021-06-01 10:29
MOT test number	111520702735
Result	✓ Passed
Advice	Both front lower sills damaged
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	All side marker lamps not working

**MOT #4**

2021-05-14 10:12

MOT test number

614825677068

Result**✗ Failed**

- Fail** Central Rear Stop lamp(s) missing (4.3.1 (a) (ii))
- Fail** Power steering pump leaking (2.1.5 (a))
- Fail** Power steering malfunctioning (2.1.5 (a))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Both front lower sills damaged
- Fail** Offside Front Side repeater missing (4.4.1 (a) (ii))
- Advice** Offside Rear brake pad sensor wire broken
- Fail** Offside Rear Brake lever has restricted free movement caliper lever jamming (1.1.15 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Brake pedal not releasing correctly (1.1.2 (b) (i))
- Advice** Front Brake pad(s) wearing thin 3-4mm (1.1.13 (a) (ii))
- Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Advice** Brake pedal rubber worn
- Fail** Offside Front Body component damaged and likely to cause injury door mirror exposing sharp edge (6.2.1 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** All nearside and offside marker lamps not working

**MOT #3** 2020-06-02 07:09**MOT test number** 541666961945**Result** ✓ Passed**MOT #2** 2019-04-09 11:13**MOT test number** 471837418788**Result** ✓ Passed**Advice** Both nsf & osf sills damaged**MOT #1** 2019-04-03 10:12**MOT test number** 848212393136**Result** ✗ Failed**Advice** Both nsf & osf sills damaged**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps x2 (4.7.1 (b) (ii))**Advice** Offside Front side marker inop**Fail** Brake pad(s) worn down to wear indicator lamp on dash (1.1.13 (a) (i))**Advice** Service lamp illuminated**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear x2 side markers inop**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Nearside Rear Brake hose slightly twisted and insecure (1.1.12 (b) (i))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
1 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-04-08
Last registration	2023-05-22
Complete history	See info



Registration #1	2016-04-08	22 mi
Registration #2	2019-04-03	60.542 mi
Registration #3	2019-04-09	60.549 mi
Registration #4	2020-06-02	86.154 mi
Registration #5	2021-05-14	103.681 mi
Registration #6	2021-06-01	103.716 mi
Registration #7	2023-05-22	103.716 mi
Registration #8	2023-05-22	103.716 mi
Registration #9	2023-05-22	103.716 mi
Registration #10	2023-05-22	103.716 mi
Registration #11	2023-05-22	103.716 mi
Registration #12	2023-05-22	103.716 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2470 mm
Height	2488 mm
Length	6198 mm
Kerb weight	1970 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	C226500