



report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Black
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2022-08-04
Pictures	12
Listing price	View report






Video viewing

Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	32
Total items failed	11

MOT #17	2023-10-04 13:44
MOT test number	303892272453
Result	✓ Passed
Next expiry date	2024-10-10
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2022-10-11 16:52
MOT test number	312364974056
Result	✓ Passed

MOT #15	2021-09-06 09:58
MOT test number	484688798862
Result	✓ Passed



MOT #14

2020-08-15 15:41

MOT test number

403530155491

Result

✓ Passed

- Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice

Rear Exhaust box outer casing corroded
- Advice

Drive belt worn, but not excessively (6.1.7 (c) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Front Tyre slightly damaged/cracking or perishing Also tyre worn on inner edge (5.2.3 (d) (ii))

**MOT #13**

2020-08-15 10:29

MOT test number

641754981584

Result**✗ Failed**

Advice Offside Front Tyre slightly damaged/cracking or perishing Also tyre worn on inner edge (5.2.3 (d) (ii))

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Drive belt worn, but not excessively (6.1.7 (c) (i))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated Upper and Lower (5.3.4 (b) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Exhaust box outer casing corroded

MOT #12

2019-08-27 11:53

MOT test number

361195891557

Result**✓ Passed**

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2019-08-27 10:26

MOT test number

731368915250

Result**✗ Failed****Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10**

2018-08-24 15:03

MOT test number

682782728518

Result**✓ Passed****MOT #9**

2018-08-24 09:13

MOT test number

152880133463

Result**✗ Failed****Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8**

2017-08-26 09:03

MOT test number

602357247635

Result**✓ Passed****Advice** Oil leak oil filter**Advice** Nearside Rear Tyre worn close to the legal limit and cracking (4.1.E.1)**Advice** Clutch release bearing very noisy



MOT #7	2016-08-25 14:18
MOT test number	394175529795
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases back box (7.1.2)

MOT #6	2016-08-25 08:21
MOT test number	459625001974
Result	✗ Failed
Pass with rectification	Nearside Stop lamp not working (1.2.1b)
Fail	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Advice	Exhaust has a minor leak of exhaust gases back box (7.1.2)
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #5	2015-08-15 11:33
MOT test number	963409804092
Result	✓ Passed

MOT #4	2014-08-23 12:27
MOT test number	876755734211
Result	✓ Passed

MOT #3	2014-08-23 10:15
MOT test number	767485434293
Result	✗ Failed
Fail	Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)



MOT #2	2013-08-17 11:30
MOT test number	978509623201
Result	✓ Passed
Notice	N/s/f tyre outer side wall has damadge
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

MOT #1	2012-09-06 15:31
MOT test number	928990852288
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-17
Last registration	2023-10-04
Complete history	See info



Registration #1	2009-09-17	8 mi
Registration #2	2012-09-06	19.237 mi
Registration #3	2013-08-17	24.437 mi
Registration #4	2014-08-23	30.158 mi
Registration #5	2014-08-23	30.158 mi
Registration #6	2015-08-15	35.876 mi
Registration #7	2016-08-25	42.806 mi
Registration #8	2016-08-25	42.806 mi
Registration #9	2017-08-26	47.168 mi
Registration #10	2018-08-24	50.357 mi
Registration #11	2019-08-24	55.357 mi
Registration #12	2019-08-24	55.357 mi
Registration #13	2019-08-24	55.357 mi
Registration #14	2019-08-24	55.357 mi
Registration #15	2019-08-24	55.357 mi
Registration #16	2019-08-24	55.357 mi
Registration #17	2019-08-24	55.357 mi
Registration #18	2019-08-24	55.357 mi
Registration #19	2019-08-24	55.357 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694