





report date: 2024-03-29

## General information

Make	HONDA
Model	HR-V I-VTEC SE
Colour	White
Year of manufacture	2018
Top speed	119 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	128 BHP
Max. torque	155 Nm at 4.600 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29


# Internet history

### Entry 2


Date 2021-06-25

Pictures 20

Listing price <u>View report</u>










source: heycar.co.uk

Entry 1

Date	2021-06-17
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



WK18XOA report date: 2024-03-29

MOT history

MOT expiry date	2025-04-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #5	2024-04-03 07:28
MOT test number	517372128295
Result	✓ Passed
Next expiry date	2025-04-09
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 215/55R17 - Michelin (5.2.3 (e))	

MOT #4		2023-04-03 07:59
MOT test	number	715279091621
Result		✓ Passed
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2022-03-25 15:54
MOT test	number	464792666516
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre

MOT #1

2021-04-09 11:50

MOT test number

585065039834

Result

X Failed

Fail Offside Rear fog lamp does not emit a steady red light lens broken, emitting a white light to rear (4.5.4 (a))

Advice Nearside Rear Nail in tyre

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Items removed from driver's view prior to test dash cam on seat

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	9 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
**************	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-24
Last registration	2024-04-03
Complete history	See info



Registration #1	2018-05-24	27 mi
Registration #2	2021-04-09	22.317 mi
Registration #3	2021-04-10	22.317 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	72%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1605 mm
Length	4294 mm
Wheel base	2610 mm
Kerb weight	1313 kg
Max. allowed weight	1790 kg

# Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	L15B43016310

CarCheck.co.uk page 11/11