





General information	
Make	VAUXHALL
Model	VIVARO 2700 L1H1 CDTI P/V SPORTIVE ECOFLEX S/S
Colour	Grey
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date Pictures 2021-08-25

18


Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #7		2023-10-02 13:33
MOT test	number	964070304380
Result		🗸 Passed
Next expiry date 2024-10-0		2024-10-06
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Advice Rear Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))	

MOT #6	2023-10-02 11:19
MOT test number	477447135574
Result	🗙 Failed
Fail Nearside Rear Tyre has ply or cords exposed bald on outer edge (5.2.3 (d) (ii))	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s	(1.1.14 (a) (ii))

MOT #5		2022-10-05 14:29
MOT test numb	ber	321820569297
Result		✓ Passed
Advice Fron (a) (ii))	nt Brake disc worn, pitted or scored, but not seriously weakened o/s and n/s in	nner faces (1.1.14



DF16YFV
report date: 2024-03-28

2021-02-08 12:38

842574336000

✓ Passed

MOT #4	2021-10-07 12:07
MOT test number	465399229548
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

Μ	ΟΤ	#3
		<i>"</i> J

MOT test number		
Result		
Advice	Rear brake disc corrosion	

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

МОТ #2	2020-02-06 13:00
MOT test number	721995188020
Result	✓ Passed

MOT #1	2019-02	2-26 09:16
MOT test	2743 2743	325123056
Result		✓ Passed
Advice	Chip's to screen	
Advice (5.2.3 (e))	Nearside Rear Tyre worn close to legal limit/worn on edge 2.5 mm worn on edge's 205/65	5/16c
Advice	Nearside Front Nail in tyre	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3.0 mm worn on edge's (5.2.3 (e	;))



Tax & MOT check

Tax due: 1 October 2024	ed	Expires: 6 October 2024	✓ МОТ
Tax status			Valid until 1 October
Days left			155
MOT expiry date			6 October 2024
Full MOT history			See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

AND	

NUMBER OF CONTRACTOR OF CONTRA	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-07-08
Last registration	2023-10-02
Complete history	<u>See info</u>



Registration #1	2016-07-08	12 mi
Registration #2	2019-02-26	65.015 mi
Registration #3	2020-02-06	88.193 mi
Registration #4	2021-02-08	106.088 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Safety ratings

NCAP rating	****	- Junice
Adult	52%	EURO
Children	91%	-
Pedestrian	53%	
Safety systems	57%	
Overall rating	61%	
Video	see crash video	



Dimensions & weight	
Width	2283 mm
Height	1970 mm
Length	4998 mm
Kerb weight	1683 kg
Max. allowed weight	2760 kg
Additional information	
Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MB - C118686LWU