





report date: 2024-03-29

### General information

Make	FORD
Model	FUSION STYLE PLUS
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-10-30

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

# MOT history

MOT expiry date	2024-10-26
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	13
Total items failed	1

MOT #14		2023-10-26 09:48
MOT test nur	nber	958852983595
Result		✓ Passed
Next expiry o	late	2024-10-26
Minor  Offside Front Lower Suspension component ball joint dust cover severely deteriorated Split (5.3.4 (b) (i))		
Advice Ex	chaust has a minor leak of exhaust gases Rear box has a small blow	(6.1.2 (a))
<b>Advice</b> Of	ffside Rear Nail in tyre	

MOT #13		2023-10-25 15:23
MOT test	number	751449144072
Result		🗙 Failed
Advice	Exhaust has a minor leak of exhaust gases Rear box has a small blow (6.1.2 (a)	)
Advice	Offside Rear Nail in tyre	
Minor (b) (i))	Offside Front Lower Suspension component ball joint dust cover severely deterio	rated Split (5.3.4
MAJOR Outer side	Offside Front Tyre has a cut in excess of the requirements deep enough to reacwall (5.2.3 (d) (i))	h the ply or cords

MOT #12	2022-10-26 09:19
MOT test number	572560898323
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11

MOT test number

668162513097

Result

Advice

O/s/r bumper slightly damaged

MOT #10

MOT test number

Result

MOT #9

2021-03-17 12:41

46118571981

✓ Passed

MOT #9

2019-10-15 08:43

MOT test number

318783425535

Result

✓ Passed

Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT test number

Franction

Minor

Offside Windscreen wiper blade defective (3.4 (b) (i))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing along the tread grooves (5.2.3 (d) (ii))

Minor

Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #7	2017-10-13 15:36
MOT test number	786418654045
Result	✓ Passed
MOT #6	2016-10-07 14:04
MOT test number	766204203400
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5	2015-10-16 15:29
MOT test number	456681713173
Result	✓ Passed
MOT #4	2014-10-23 09:31
MOT test number	575926694287
Result	✓ Passed
Notice All tyres slightly perished & front tyres worn slighty on inner edges	

MOT #3	2013-10-09 09:32
MOT test number	146562583248
Result	✓ Passed
MOT #2	2012-10-03 12:31
MOT test number	795787372225

Result	✓ Passed
MOT #1	2012-10-03 12:17
MOT test number	566747772261

Result × Failed

Fail Offside Rear Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/12



FN59GYP
report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owr		bi-	+~	100
UMMI	1er	mis	TO	II V

e union matery	
For how long did the current and previous owner(s) have this FORD? How many owners Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NE NK
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-01
Last registration	2023-10-26
Complete history	See info



Registration #1	2009-09-01	19 mi
Registration #2	2012-10-03	18.505 mi
Registration #3	2012-10-03	18.505 mi
Registration #4	2013-10-09	23.853 mi
Registration #5	2014-10-23	28.949 mi
Registration #6	2015-10-16	34.375 mi
Registration #7	2016-10-07	39.117 mi
Registration #8	2017-10-13	42.973 mi
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		11.177 mi
Registration #14		11.117 es
Registration #15		11.177 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1922 mm
Height	1481 mm
Length	3958 mm
Wheel base	2489 mm
Kerb weight	966 kg
Max. allowed weight	1530 kg

## Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles2Engine number9J10615