




report date: 2024-03-29

General information

Make	CITROEN
Model	C2 GT 16V
Colour	Silver
Year of manufacture	2004
Top speed	121 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-29
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-08-03
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	60
Total items failed	29

MOT #23	2022-07-28 17:08
MOT test number	339569860850
Result	✓ Passed
Next expiry date	2023-08-03
Advice	Exhaust noisy (8.1.1 (a))

MOT #22	2021-08-04 11:07
MOT test number	993632524733
Result	✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))
Advice	Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))

MOT #21	2020-07-21 08:09
MOT test number	408259943161
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))

**MOT #20** 2020-07-21 08:09**MOT test number** 126427304193**Result** ✗ Failed**Pass with rectification** Offside Side repeater not working (4.4.1 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #19** 2019-07-01 12:40**MOT test number** 465855598373**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Central Front Brake pipe corroded, covered in grease or other material Front to Rear brake pipes corroded but not excessive (1.1.11 (c))**MOT #18** 2018-07-13 10:56**MOT test number** 497951742095**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Brake pipe corroded, covered in grease or other material both main (1.1.11 (c))**Advice** Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))



MOT #17

2017-07-27 11:23

MOT test number

621642915107

Result		✓ Passed
Advice	Nearside Brake pipe slightly corroded Front to rear (3.6.B.2c)	
Advice	Front number plate damaged	
Advice	Brake pipe slightly corroded A.B.S pump brake pipes (3.6.B.2c)	
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)	
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)	

**MOT #16**

2017-07-24 09:08

MOT test number

564030809089

Result**✗ Failed****Advice** Brake pipe slightly corroded A.B.S pump brake pipes (3.6.B.2c)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside front brake excessively fluctuating (3.7.B.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Brake pipe slightly corroded Front to rear (3.6.B.2c)**Advice** Front number plate damaged**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside front brake excessively fluctuating (3.7.B.3)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Brake pipe slightly corroded Front to rear (3.6.B.2c)**MOT #15**

2016-07-21 15:49

MOT test number

847729697009

Result**✓ Passed****Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #14	2016-07-20 11:52
MOT test number	427037901681
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
Advice	Centre Exhaust has a minor leak of exhaust gases (7.1.2)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front Inner brake disc in such a condition that it is seriously weakened (3.5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front Inner brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #13	2015-03-18 10:37
MOT test number	185167375063
Result	✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12**

2015-03-10 13:00

MOT test number

995619765043

Result

✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Rear fog lamp not working (1.3.2b)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)

MOT #11

2014-02-04 16:35

MOT test number

776045134074

Result

✓ Passed

- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

MOT #10

2014-02-03 09:27

MOT test number

196014334409

Result

✗ Failed

- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Front wheel bearing has excessive play (2.5.A.3c)
- Fail** Rear Exhaust system not adequately supported (7.1.1)

MOT #9

2013-01-18 12:10

MOT test number

248548713020

Result

✓ Passed

**MOT #8** 2011-09-21 15:58**MOT test number** 278794761247**Result** ✓ Passed

- Notice** Rear silencer outer skin peeling
- Notice** O/s/f tyre getting low
- Notice** N/s/f tyre low
- Notice** N/s/r tyre wall/tread cracked (not to cords) tread low and nail in.

MOT #7 2011-09-21 12:33**MOT test number** 147634061291**Result** ✗ Failed

- Notice** N/s/r tyre wall/tread cracked (not to cords) tread low and nail in.
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Rear silencer outer skin peeling
- Notice** O/s/f tyre getting low
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** N/s/f tyre low

MOT #6 2010-09-20 16:18**MOT test number** 431433760267**Result** ✓ Passed

- Notice** Rear silencer outer skin peeling
- Notice** N/s/r tyre wall cracked

**MOT #5** 2010-09-20 12:41**MOT test number** 313813160457**Result** ✗ Failed**Notice** Rear silencer outer skin peeling**Fail** Nearside Direction indicators incorrect colour (1.4.A.2f)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Notice** N/s/r tyre wall cracked**Fail** Rear Stop lamp not working (1.2.1b)**MOT #4** 2009-09-15 14:50**MOT test number** 920078659237**Result** ✓ Passed**MOT #3** 2008-09-19 15:02**MOT test number** 660733468238**Result** ✓ Passed**MOT #2** 2008-09-19 10:19**MOT test number** 103103468208**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Side repeater incorrect colour (1.4.A.2f)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2007-09-14 15:49
MOT test number	890567157264
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 January 2024

X

MOT

Expired:
3 August 2023

Tax status	Expired at 1 January 2024
Days left	120 days too late
MOT expiry date	3 August 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-09-22
Last registration	2022-07-28
Complete history	See info



Registration #1	2004-09-22	20 mi
Registration #2	2007-09-14	19.905 mi
Registration #3	2008-09-19	23.193 mi
Registration #4	2008-09-19	23.193 mi
Registration #5	2009-09-15	27.258 mi
Registration #6	2010-09-20	30.894 mi
Registration #7	2010-09-20	30.894 mi
Registration #8	2011-09-21	35.482 mi
Registration #9	2011-09-21	35.482 mi
Registration #10	2013-01-18	45.079 mi
Registration #11	2014-02-03	54.549 mi
Registration #12	2014-02-04	54.549 mi
Registration #13	2015-03-10	65.296 mi
Registration #14	2015-03-10	65.296 mi
Registration #15	2015-03-10	65.296 mi
Registration #16	2015-03-10	65.296 mi
Registration #17	2015-03-10	65.296 mi
Registration #18	2015-03-10	65.296 mi
Registration #19	2015-03-10	65.296 mi
Registration #20	2015-03-10	65.296 mi
Registration #21	2015-03-10	65.296 mi
Registration #22	2015-03-10	65.296 mi
Registration #23	2015-03-10	65.296 mi
Registration #24	2015-03-10	65.296 mi
Registration #25	2015-03-10	65.296 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1027 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	FX4Z2203115