





report date: 2024-03-28

General information

Make	RENAULT
Model	MASTER MM35 BUSINESS PLUS DCI S/R P/V
Colour	White
Year of manufacture	2016
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.500 rpm
Engine capacity	2.298 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	36.2 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-05-18

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2022-04-26

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-25
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	14
Total items failed	13

MOT #8		2023-06-26 06:41
MOT test	number	863806253704
Result		✓ Passed
Next exp	iry date	2024-06-25
Advice	Offside Rear Tyre worn close to legal limit/worn on edge outer edge worn. 2	225/65R16C (5.2.3 (e))
Minor	Offside Rear Brake hose slightly twisted (1.1.12 (b) (i))	
Minor	Nearside Side repeater lens defective which has no effect on emitted light (4	1.4.1 (b) (i))

MOT #7	2023-06-15 13:51
MOT test number	874133267252
Result	★ Failed
Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lan	nps (4.7.1 (b) (ii))
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Minor Offside Rear Brake hose slightly twisted (1.1.12 (b) (i))	
Fail Fuel tank leaking (6.1.3 (b) (i))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick on metal (1.1.13 (a) (ii))	
Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4)	4.1 (b) (i))
Advice Offside Rear Tyre worn close to legal limit/worn on edge outer edge worn. 22	25/65R16C (5.2.3 (e))

CarCheck.co.uk page 3/12



MOT #6 2022-03-15 14:02

MOT test number 783245189069

Result ✓ Passed

Advice Staining on underside of van around fuel tank and floor pan and suspension components

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

Advice Brake pedal rubber worn

Advice Nearside Front Lower caliper slide dust cover missing

MOT #5 2021-03-26 13:48

MOT test number 446788265794

Result ✓ Passed

MOT #4 2021-03-18 09:13

MOT test number 114638000078

Result X Failed

Fail Driver's seat moving inadvertently (6.2.5 (b) (ii))

Fail Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Fuel tank leaking (6.1.3 (b) (i))

CarCheck.co.uk page 4/12



Result

LX16HXL report date: 2024-03-28

× Failed

MOT #3 2020-03-17 14:24

MOT test number 523197090310

Result ✓ Passed

Advice Offside Front Tyre slightly damaged tread (5.2.3 (d) (ii))

Advice Wear on brake pedal rubber

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-03-25 14:25

MOT test number 940294042257

Result
✓ Passed

MOT #1 2019-03-25 14:25

MOT test number 947864088682

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Pass with rectification Central Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

o mile motory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
THE STATE OF THE S	

manage of the same	

	More info >
Plate changes	
Coo in this chook if this DEMALLET had different purchase plates	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK ON THE STATE OF
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-29
Last registration	2023-06-26
Complete history	See info



Registration #1	2016-03-29	28 mi
Registration #2	2019-03-25	27.678 mi
Registration #3	2019-03-25	27.678 mi
Registration #4	2020-03-17	36.074 mi
Registration #5	2021-03-18	45.118 mi
Registration #6	2021-03-26	45.118 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		10.377 esc

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	2470 mm
Height	2499 mm
Length	5548 mm
Wheel base	3682 mm
Kerb weight	1910 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	C195966

CarCheck.co.uk page 12/12