



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI SW SPORT
Colour	Grey
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-12-12
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	76
Total items failed	12

MOT #19 2023-12-11 09:04

MOT test number 467900030449

Result ✓ Passed

Next expiry date 2024-12-12

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Minor Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18 2022-12-13 17:28

MOT test number 452669712206

Result ✓ Passed

Advice Offside Side repeater slightly discoloured (4.4.3 (a))

Advice Front Exhaust mounting defective (6.1.2 (a))

**MOT #17**

2022-12-09 11:00

MOT test number

298291177945

Result**✗ Failed**

- Advice** Front Exhaust mounting defective (6.1.2 (a))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))

MOT #16

2021-12-07 14:39

MOT test number

910562275050

Result**✓ Passed**

- Advice** Central Exhaust mounting defective hanger breaking off from the exhaust (6.1.2 (a))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking 195/55/16 (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner and outer edges worn 195/55/16 (5.2.3 (e))



MOT #15

2021-12-03 12:11

MOT test number

946716326912

Result

✖ Failed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking 195/55/16 (5.2.3 (d) (ii))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn wishbone ball joint (5.3.4 (a) (i))
- Advice** Central Exhaust mounting defective hanger breaking off from the exhaust (6.1.2 (a))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner and outer edges worn 195/55/16 (5.2.3 (e))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14**

2021-12-01 09:47

MOT test number

908094004291

Result**✗ Failed**

MAJOR Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor Offside Front Brake hose slightly twisted (1.1.12 (b) (i))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Exhaust mounting defective centre (6.1.2 (a))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Side repeater slightly discoloured (4.4.3 (a))

MOT #13

2020-12-09 12:20

MOT test number

872811978788

Result**✓ Passed**

**MOT #12** 2020-12-04 09:58**MOT test number** 392419917492**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Brake hose excessively chafed (1.1.12 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust mounting defective middle and back (6.1.2 (a))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2019-12-05 16:16**MOT test number** 212402964341**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2018-12-10 14:02

MOT test number

799384739115

Result

✓ Passed

- Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Manifold heat shield loose.
- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Tyre worn on edges.
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Tow bar corroded.

MOT #9

2018-03-03 08:35

MOT test number

674257351994

Result

✓ Passed

MOT #8

2018-03-02 13:49

MOT test number

683715978581

Result

✗ Failed

- Fail** Offside Headlamp aim too high (1.8)
- Fail** Nearside Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Nearside Headlamp aim too high (1.8)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #7** 2017-04-12 10:25**MOT test number** 134884224617**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-04-12 10:25**MOT test number** 160992847653**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-04-06 11:51**MOT test number** 529719891559**Result** ✓ Passed**Advice** Oil leak**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Covers and trays fitted

**MOT #4** 2016-04-06 11:51**MOT test number** 941269008407**Result** ✗ Failed**Pass with rectification** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Oil leak**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Covers and trays fitted**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-04-15 10:02**MOT test number** 306245905103**Result** ✓ Passed**MOT #2** 2014-03-28 16:52**MOT test number** 337797384041**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #1** 2013-03-27 14:33**MOT test number** 907626483067**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Items removed from driver's view prior to test**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KY10YMK
Plate since	2010-09-29
Current registration	KY10YMK
Plate since	2010-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	21
First mileage registration	2010-03-08
Last registration	2023-12-11
Complete history	See info



Registration #1	2010-03-08	24 mi
Registration #2	2013-03-27	38.929 mi
Registration #3	2014-03-28	49.062 mi
Registration #4	2015-04-15	60.569 mi
Registration #5	2016-04-06	71.355 mi
Registration #6	2016-04-06	71.355 mi
Registration #7	2017-04-12	82.386 mi
Registration #8	2017-04-12	82.386 mi
Registration #9	2018-03-02	92.506 mi
Registration #10	2018-03-03	92.506 mi
Registration #11	2018-12-10	97.140 mi
Registration #12	2019-03-29	97.140 mi
Registration #13	2019-03-29	97.140 mi
Registration #14	2019-03-29	97.140 mi
Registration #15	2019-03-29	97.140 mi
Registration #16	2019-03-29	97.140 mi
Registration #17	2019-03-29	97.140 mi
Registration #18	2019-03-29	97.140 mi
Registration #19	2019-03-29	97.140 mi
Registration #20	2019-03-29	97.140 mi
Registration #21	2019-03-29	97.140 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4156 mm
Wheel base	2540 mm
Kerb weight	1332 kg
Max. allowed weight	1741 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBBX0016147