



report date: 2024-03-28

General information

Make	VAUXHALL
Model	TIGRA SRI 16V
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



MOT history

MOT #22 2021-11-16 16:57

MOT test number 744877868225

Result ✓ Passed

Next expiry date 2022-11-15

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Outer Side repeater slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive Gearbox leak (8.4.1 (a) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Oil leak, but not excessive Sump pan (8.4.1 (a) (i))

**MOT #21**

2021-11-08 15:58

MOT test number

451519993273

Result**✗ Failed**

- Advice** Oil leak, but not excessive Gearbox leak (8.4.1 (a) (i))
- Advice** Nearside Front Outer Side repeater slightly discoloured (4.4.3 (a))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive Sump pan (8.4.1 (a) (i))
- MAJOR** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #20

2020-07-22 10:37

MOT test number

132577246528

Result**✓ Passed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #19** 2020-07-22 08:22**MOT test number** 118670746316**Result** ✗ Failed**DANGEROUS** Nearside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**DANGEROUS** Nearside Rear Brake valve leaking such that brake functionality is affected (1.1.7 (d) (ii))**MOT #18** 2019-07-15 11:30**MOT test number** 700331515939**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #17** 2019-07-15 08:59**MOT test number** 844516526243**Result** ✗ Failed**MAJOR** Windscreen wiper not working (3.4 (a))**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Windscreen washer not working (3.5 (a))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #16**

2018-07-25 09:01

MOT test number

354674946099

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15**

2018-05-18 15:10

MOT test number

617509598945

Result

✓ Passed

Advice Front Macpherson strut has slight movement at the upper attachment both side (2.5.A.1c)**Advice** Front Brake pipe slightly corroded both side (3.6.B.2c)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both side (3.5.1i)**MOT #14**

2018-05-17 08:32

MOT test number

745133590072

Result

✗ Failed

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both side (3.5.1i)**Fail** Offside Front coil spring inappropriately repaired (2.4.A.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Macpherson strut has slight movement at the upper attachment both side (2.5.A.1c)**Advice** Front Brake pipe slightly corroded both side (3.6.B.2c)**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

**MOT #13**

2017-06-21 08:46

MOT test number

813728629844

Result

✓ Passed

- Advice** Offside Front tyre worn
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front tyre worn on edge
- Advice** Nearside Rear tyre worn
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front coil spring corroded (2.4.C.1b)

MOT #12

2017-06-19 11:45

MOT test number

621418490492

Result

✗ Failed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Front tyre worn
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Front tyre worn on edge
- Advice** Nearside Rear tyre worn

MOT #11

2016-06-13 12:39

MOT test number

925659557535

Result

✓ Passed

- Advice** Nearside Front tyre worn
- Advice** Front brake discs worn

**MOT #10** 2015-06-12 16:33**MOT test number** 447473965128**Result** ✓ Passed**MOT #9** 2014-06-09 09:22**MOT test number** 415280264152**Result** ✓ Passed**MOT #8** 2013-04-27 10:27**MOT test number** 426767813116**Result** ✓ Passed**Notice** Tyres starting to perish**MOT #7** 2012-05-12 11:25**MOT test number** 229003732138**Result** ✓ Passed**MOT #6** 2011-05-14 12:56**MOT test number** 428354631130**Result** ✓ Passed**MOT #5** 2010-06-02 14:49**MOT test number** 212263850461**Result** ✓ Passed**MOT #4** 2010-06-01 15:02**MOT test number** 454462750106**Result** ✗ Failed**Fail** Offside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Fail** Nearside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)



MOT #3	2009-05-30 12:18
MOT test number	983230759158
Result	✓ Passed

MOT #2	2009-05-30 10:04
MOT test number	594780259117
Result	✗ Failed
<div><div>Fail</div>Offside Front Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)</div>	

MOT #1	2008-06-27 14:34
MOT test number	294329178120
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KK05VRT
Plate since	2024-03-28
Current registration	 KK05VRT
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-07-29
Last registration	2021-11-16
Complete history	See info



Registration #1	2005-07-29	23 mi
Registration #2	2008-06-27	13.164 mi
Registration #3	2009-05-30	17.094 mi
Registration #4	2009-05-30	17.094 mi
Registration #5	2010-06-01	21.070 mi
Registration #6	2010-06-02	21.070 mi
Registration #7	2011-05-14	25.465 mi
Registration #8	2012-05-12	30.074 mi
Registration #9	2013-04-27	35.338 mi
Registration #10	2014-06-09	44.080 mi
Registration #11	2015-06-12	49.873 mi
Registration #12	2016-06-13	54.253 mi
Registration #13	2016-06-13	54.253 mi
Registration #14	2016-06-13	54.253 mi
Registration #15	2016-06-13	54.253 mi
Registration #16	2016-06-13	54.253 mi
Registration #17	2016-06-13	54.253 mi
Registration #18	2016-06-13	54.253 mi
Registration #19	2016-06-13	54.253 mi
Registration #20	2016-06-13	54.253 mi
Registration #21	2016-06-13	54.253 mi
Registration #22	2016-06-13	54.253 mi
Registration #23	2016-06-13	54.253 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3817 mm
Wheel base	2491 mm
Kerb weight	1133 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	19FC6425