



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI QUICKSHIFT
Colour	Black
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	180 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-10-13
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	15
Total items failed	17

MOT #14	2023-09-21 15:03
MOT test number	673541724900
Result	✓ Passed
Next expiry date	2024-09-20
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))



MOT #13

2023-09-12 10:28

MOT test number

915246376212

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Coolant level low
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure 215/65r16 (5.2.3 (d) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Front Registration plate inscription illegible (0.1 (b))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #12

2022-09-20 11:26

MOT test number

307031959737

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Front washers weak, still provide sufficient fluid to screen

MOT #11

2021-09-17 08:24

MOT test number

522515823474

Result

✓ Passed

**MOT #10** 2020-08-20 12:34**MOT test number** 727731899641**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**MOT #9** 2020-08-20 07:54**MOT test number** 992211548164**Result** ✗ Failed**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Inner Anti-roll bar pin or bush excessively worn D-bush. (5.3.4 (a) (i))**Fail** Offside Rear Outer Seat belt buckle not functioning as intended (7.1.2 (d))**Fail** Offside Front Inner Anti-roll bar pin or bush excessively worn D-bush. (5.3.4 (a) (i))**Advice** Play in steering rack inner joint(s)**MOT #8** 2019-08-13 10:35**MOT test number** 938171287370**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-08-10 11:03**MOT test number** 759757849306**Result** ✓ Passed**MOT #6** 2017-08-08 11:36**MOT test number** 664801527058**Result** ✓ Passed

**MOT #5** 2017-08-08 09:01**MOT test number** 824169721071**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear Nail in tyre**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2016-08-23 11:35**MOT test number** 724871531417**Result** ✓ Passed**MOT #3** 2016-08-18 10:53**MOT test number** 434896688972**Result** ✗ Failed**Fail** Nearside Rear Body insecure and dangerous to other road users quarter bumper split eight inches of panel protruding (6.1.B.1b)**Fail** Nearside Rear Rear position lamp(s) excessively damaged so that it is not visible from a reasonable distance (1.1.A.3d)**MOT #2** 2015-11-05 13:06**MOT test number** 859163124494**Result** ✓ Passed**MOT #1** 2015-01-12 12:48**MOT test number** 739332415076**Result** ✓ Passed**Notice** Front wiper blades split**Notice** Nail in o/s/f tyre



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 September 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	20 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 MONTHS
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-01
Last registration	2023-09-21
Complete history	See info



Registration #1	2012-03-01	10 mi
Registration #2	2015-01-12	16.038 mi
Registration #3	2015-11-05	20.169 mi
Registration #4	2016-08-18	23.894 mi
Registration #5	2016-08-23	23.995 mi
Registration #6	2017-08-08	51.981 mi
Registration #7	2017-08-08	51.981 mi
Registration #8	2018-08-10	90.609 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Engine number	C007558