



SB08YBE

report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 16V
Colour	Black
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	256 BHP
Max. torque	380 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	34.9 mpg
Consumption combined	27.7 mpg



LABEL UNKNOWN

**MOT history****MOT #16** 2021-01-13 12:39**MOT test number** 780042979732**Result** ✗ Failed

- MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Under trays fitted
- MAJOR** Rear Exhaust silencer insecure (8.1.1 (b) (i))

MOT #15 2020-08-10 10:32**MOT test number** 133008421695**Result** ✓ Passed

- Advice** Nearside Rear Upper Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Under trays fitted to vehicle
- Advice** Offside Rear Upper Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #14 2019-09-06 14:47**MOT test number** 602254660179**Result** ✓ Passed**MOT #13** 2019-09-06 11:59**MOT test number** 734440853453**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 235/60R18 (5.2.3 (e))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm 235/60R18 (5.2.3 (e))

**MOT #12** 2018-08-28 15:44**MOT test number** 879631097459**Result** ✓ Passed**MOT #11** 2018-01-08 15:20**MOT test number** 641464582288**Result** ✓ Passed**MOT #10** 2017-01-30 12:46**MOT test number** 619359272204**Result** ✓ Passed**MOT #9** 2017-01-19 11:46**MOT test number** 746728043782**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #8** 2016-01-26 13:32**MOT test number** 500401301288**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2016-01-21 13:36**MOT test number** 811140223844**Result** ✗ Failed**Fail** Offside Front Track rod end ball pin shank loose (2.2.B.1c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Anti-roll bar locating pin insecure (2.4.G.3a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-01-30 11:03**MOT test number** 856410135070**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2014-01-28 15:02**MOT test number** 588218024015**Result** ✓ Passed**MOT #4** 2014-01-24 08:53**MOT test number** 187734224499**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Fail** Nearside Front Headlamp aim too low (1.8)**Notice** N/s/f/ light levler broken**Fail** Offside Front Headlamp aim too low (1.8)



MOT #3	2013-05-29 10:57
MOT test number	369449843192
Result	✓ Passed
<div>NoticeBoth front disks worn on inner sides</div>	

MOT #2	2012-05-23 20:17
MOT test number	686024042174
Result	✓ Passed

MOT #1	2011-05-27 14:17
MOT test number	938457841148
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-31
Last registration	2021-01-13
Complete history	See info



Registration #1	2008-05-31	19 mi
Registration #2	2011-05-27	31.596 mi
Registration #3	2012-05-23	40.677 mi
Registration #4	2013-05-29	48.364 mi
Registration #5	2014-01-24	53.904 mi
Registration #6	2014-01-28	53.904 mi
Registration #7	2015-01-30	59.272 mi
Registration #8	2016-01-21	64.099 mi
Registration #9	2016-01-26	64.114 mi
Registration #10	2016-01-26	64.114 mi
Registration #11	2016-01-26	64.114 mi
Registration #12	2016-01-26	64.114 mi
Registration #13	2016-01-26	64.114 mi
Registration #14	2016-01-26	64.114 mi
Registration #15	2016-01-26	64.114 mi
Registration #16	2016-01-26	64.114 mi
Registration #17	2016-01-26	64.114 mi

More info >



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4680 mm
Wheel base	2750 mm
Kerb weight	1695 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L3 20279163