





General information

Make	AUDI
Model	A4 S LINE TDI DPF
Colour	Silver
Year of manufacture	2007
Top speed	138 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry	1
Date	

Pictures

2021-06-03

26

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-27
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	16
Total items failed	4

MOT #14 20	023-05-23 15:57
MOT test number	627188816281
Result	🗸 Passed
Next expiry date	2024-05-27
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #13	2022-05-19 08:55
MOT test number	643192510911
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #12		2021-05-28 15:30
MOT test numb	er	442010637298
Result		✓ Passed
Advice Offsi	ide Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		





MOT #11	2020-05-04 09:09
MOT test number	348222924084
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps (4.7.1 (b) (i))	or light sources
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2018-10-03 20:30
MOT test number	375579338664
Result	✓ Passed

MOT #9	2017-09-05 14:54
MOT test number	322636759919
Result	✓ Passed
Advice Front Tyre worn close to the legal limit Both front worn close to limit (4.1.E.1)	

МОТ #8	2016-07-23 10:54
MOT test number	781605253638
Result	✓ Passed
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)	

MOT #7	2015-04-01 11:05
MOT test number	915681695044
Result	✓ Passed

MOT #6	2014-04-03 09:54
MOT test number	158493694438
Result	✓ Passed
Notice Advise nearside rear tyre wall slight damage outer wall	



FT07L	KN
report date: 20)24-03-29

MOT #5		2013-04-11 13:00
MOT test	number	907941103145
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

МОТ #4	2013-04-10 10:47
MOT test number	619130203120
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Stop lamp not working (1.2.1b)	
Fail Nearside Outer Rear Rear position lamp(s) not working (1.1.A.3b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Stop lamp not working (1.2.1b)	
Fail Offside Outer Rear Rear position lamp(s) not working (1.1.A.3b)	

MOT #3	2012-07-09 11:51
MOT test number	928541092198
Result	✓ Passed
MOT #2	2011-07-04 12:55
MOT test number	999905081167

Result

CarCheck.co.uk

✓ Passed





MOT #1	2010-07-08 14:00
MOT test number	631739480137
Result	✓ Passed
NoticeChild seat fitted not allowing full inspection of adult beltAdviceOffside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 27 May 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			93
MOT expiry date			27 May 2024
Full MOT history			<u>See MOT history</u>
Tax calculation			

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		ASMPL
Date		
Category	10000000	AMPL
Туре		

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-07-11
Last registration	2023-05-23
Complete history	See info



Registration #1	2007-07-11	15 mi
Registration #2	2010-07-08	25.996 mi
Registration #3	2011-07-04	31.889 mi
Registration #4	2012-07-09	37.820 mi
Registration #5	2013-04-10	42.921 mi
Registration #6	2013-04-11	42.921 mi
Registration #7	2014-04-03	50.989 mi
Registration #8	2015-04-01	59.773 mi
Registration #9		11.777 mi
Devictuation #10		
Registration #10		11.777 au
Registration #10		11.777 es
		01,000 est 01,000 est 01,000 est
Registration #11		01,000 es
Registration #11 Registration #12		01,000 es
Registration #11 Registration #12 Registration #13		01,007 46 01,007 46 01,007 46 01,007 46 01,007 46 01,007 46





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2648 mm
Kerb weight	1510 kg
Max. allowed weight	2060 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	BRD 005950