





report date: 2024-03-29

#### General information

Make	CITROEN
Model	C4 CACTUS PURETECH FLAIR
Colour	Grey
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

## MOT history

MOT expiry date	2024-09-21
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	3

MOT #6		2023-09-11 09:46
MOT test number		825826773824
Result		✓ Passed
Next expiry date		2024-09-21
<b>Advice</b> Rear T (5.2.3 (d) (ii))	yre slightly damaged/cracking or perishing RE	EAR TYRES, CRACKING, NO CORDS EXPOSED.
<b>Advice</b> Child S	eat fitted not allowing full inspection of adult	belt O/S/R AND N/S/R. CHILD SEATS FITTED.

MOT #5		2022-09-21 14:37
MOT test	number	515091896392
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

**MOT #4** 2022-09-20 09:14 **MOT** test number 539918025086 Result × Failed Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e)) Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e)) Front Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #3** 2021-09-22 11:56 **MOT** test number 497060396943 ✓ Passed Result Nearside Front Tyre slightly damaged/cracking or perishing SIDEWALL CRACKING, NO CORDS Advice EXPOSED. (5.2.3 (d) (ii)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened LIPPED AND WORN. (1.1.14 (a) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing SIDEWALL CRACKING, NO CORDS EXPOSED. (5.2.3 (d) (ii)) Offside Front Brake disc worn, pitted or scored, but not seriously weakened LIPPED AND WORN. **Advice** (1.1.14 (a) (ii))

 MOT #2
 2020-12-20 13:52

 MOT test number
 644889527504

 Result
 ✓ Passed

MOT #1 2020-07-31 14:29

MOT test number 786199714866

Result ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 21 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 September 2024
Full MOT history	See MOT history

#### Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

Owner mistory	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
**************************************	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-08-18
Last registration	2023-09-11
Complete history	See info



Registration #1	2017-08-18	12 mi
Registration #2	2020-07-31	18.466 mi
Registration #3	2020-12-20	21.041 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	82%
Children	79%
Pedestrian	80%
Safety systems	56%
Overall rating	76%
Video	see crash video

## Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2170099584

CarCheck.co.uk page 11/11