



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | CORSA GRIFFIN |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 104 mph |
| 0 - 60 mph | 15.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 74 BHP |
| Max. torque | 130 Nm at 4.000 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 43.5 mpg |
| CO2 emission | 131 g/km |
| CO2 label | E |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-05 |
| Pictures | 19 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-02-22 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #6 | 2024-02-14 13:22 |
| MOT test number | 383363049115 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-22 |
| Advice | Oil leak, but not excessive Gear selector seal leaking (8.4.1 (a) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|--|
| MOT #5 | 2023-02-23 12:06 |
| MOT test number | 712881438211 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive Rocker cover and Gear selector mechanism (8.4.1 (a) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

**MOT #4**

2023-02-22 13:53

MOT test number

393665753405

Result**✗ Failed****Advice** Oil leak, but not excessive Rocker cover and Gear selector mechanism (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
Also leaking from the split (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3**

2022-02-21 16:59

MOT test number

393826431179

Result**✓ Passed****Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))**MOT #2**

2021-11-17 14:28

MOT test number

779183223660

Result**✓ Passed****MOT #1**

2021-11-17 14:28

MOT test number

752599886010

Result**✗ Failed****Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 February 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 22 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2024-03-29 |
| Current registration | ***** |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2018-10-29 |
| Last registration | 2024-02-14 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-10-29 | 7 mi |
| Registration #2 | 2021-11-17 | 14.725 mi |
| Registration #3 | 2021-11-17 | 14.725 mi |
| Registration #4 | 2022-05-29 | 25,377 mi |
| Registration #5 | 2022-05-29 | 25,377 mi |
| Registration #6 | 2022-05-29 | 25,377 mi |
| Registration #7 | 2022-05-29 | 25,377 mi |
| Registration #8 | 2022-05-29 | 25,377 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 79% |
| Children | 77% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 72% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1736 mm |
| Height | 1479 mm |
| Length | 4021 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1066 kg |
| Max. allowed weight | 1600 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B14XER -19UC7732LDD |