





report date: 2024-03-28

General information

Make	BMW
Model	525 525D SE TOURING
Colour	Blue
Year of manufacture	2011
Top speed	143 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	450 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-10-18

Pictures 2

Listing price <u>View report</u>





source: cargurus.co.uk

Entry 1

Date	2021-06-29	
Pictures	2	
Listing price	View report	





source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2023-12-16
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	26
Total items failed	2

MOT #10		2022-12-17 09:34
MOT test	number	773396049497
Result		✓ Passed
Next expi	ry date	2023-12-16
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	

MOT #9	2021-12-14 12:10
MOT test number	732384437492
Result	√ Passed

CarCheck.co.uk page 3/12



MOT #8 2021-01-12 14:55

MOT test number 843398517721

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2021-01-12 14:55

MOT test number 963327917128

Result × Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #6 2020-01-20 16:48

MOT test number 624353709456

Result ✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-07-10 09:39

MOT test number 883128241283

Result \rightarrow Passed

Advice Offside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2017-07-11 13:21

MOT test number 384339612148

Result
✓ Passed

MOT #3 2017-01-28 11:57

MOT test number 216847989477

Result
✓ Passed

MOT #2 2016-02-01 09:24

MOT test number 897213688024

Advice Both rear tyres worn low on tread

CarCheck.co.uk page 5/12



MOT #1

MOT test number

719937344214

Result

Notice REAR TYRES SLIGHTLY WEARING ON INNER EDGES

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
	Piore inio /
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-14
Last registration	2022-12-17
Complete history	See info



Registration #1	2011-03-14	12 mi
Registration #2	2014-09-04	14.621 mi
Registration #3	2016-02-01	29.221 mi
Registration #4	2017-01-28	40.476 mi
Registration #5	2017-07-11	43.770 mi
Registration #6	2018-07-10	58.611 mi
Registration #7	2020-01-20	72.128 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
50482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	53%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1488 mm
Length	4907 mm
Wheel base	2968 mm
Kerb weight	1770 kg
Max. allowed weight	2420 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 34137671