



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI CC DSG
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	8.1 mpg
Consumption extra urban	5.1 mpg
Consumption combined	6.2 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-12-17
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #12 2020-12-18 12:10

MOT test number 435027133215

Result ✓ Passed

Next expiry date 2021-12-17

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-12-17 10:32

MOT test number 885428866483

Result ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2019-12-05 10:52**MOT test number** 463251611915**Result** ✓ Passed**MOT #9** 2018-12-04 10:18**MOT test number** 860987147707**Result** ✓ Passed**Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened on inner faces (1.1.14 (a) (ii))**MOT #8** 2017-11-27 10:18**MOT test number** 605204320857**Result** ✓ Passed**MOT #7** 2016-12-09 15:36**MOT test number** 153021304292**Result** ✓ Passed**MOT #6** 2016-12-09 10:53**MOT test number** 886415440792**Result** ✗ Failed**Advice** Exhaust clamp loose**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2015-12-07 09:09**MOT test number** 301184776492**Result** ✓ Passed



MOT #4	2014-12-10 10:47
MOT test number	858654744322
Result	✓ Passed
MOT #3	2013-12-13 09:17
MOT test number	107657243382
Result	✓ Passed
MOT #2	2013-02-25 14:32
MOT test number	108006053449
Result	✓ Passed
MOT #1	2011-11-28 12:02
MOT test number	999482431373
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
19 August 2021

X

MOT

Expired:
17 December 2021

Tax status	Expired at 19 August 2021
Days left	984 days too late
MOT expiry date	17 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SY58LSV
Plate since	2019-03-29
Current registration	 SY58LSV
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-11-21
Last registration	2020-12-18
Complete history	See info



Registration #1	2008-11-21	9 mi
Registration #2	2011-11-28	55.018 mi
Registration #3	2013-02-25	65.403 mi
Registration #4	2013-12-13	70.478 mi
Registration #5	2014-12-10	75.601 mi
Registration #6	2015-12-07	89.582 mi
Registration #7	2016-12-09	97.338 mi
Registration #8	2019-05-20	101.277 mi
Registration #9	2019-05-20	101.277 mi
Registration #10	2019-05-20	101.277 mi
Registration #11	2019-05-20	101.277 mi
Registration #12	2019-05-20	101.277 mi
Registration #13	2019-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1485 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	CBA 129434