





report date: 2024-03-29

General information

| Make | MAZDA |
|---------------------|----------------|
| Model | 3 SPORT NAV |
| Colour | Blue |
| Year of manufacture | 2018 |
| Top speed | 121 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 210 Nm at 4.000 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 43.5 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-03

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT expiry date | 2025-02-24 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 1 |

| MOT #5 | 2024-02-22 08:43 |
|--|------------------|
| MOT test number | 754456957213 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-24 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Rear Service brake binding but not excessively Both sides (1.2.1 (f)) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #4 | 2023-02-17 16:49 |
|-----------------|------------------|
| MOT test number | 905479333061 |
| Result | ✓ Passed |

MOT #3 2023-02-17 16:00

MOT test number 626786816730

Result ★ Failed

Fail Offside Front Inner Tyre has a lump, caused by separation or partial failure of its structure Sidewall (5.2.3 (d) (ii))

| MOT #2 | 2022-02-25 09:47 |
|--|------------------|
| MOT test number | 465346645346 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1 2021-03-10 10:14

MOT test number 258927305359

Result ✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



BN18AXC report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 32 |
| MOT expiry date | 24 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full | |
|---|-------------|
| | |
| | |
| *************************************** | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | IIK SIN |
| Plate since | |
| Current registration | NK SIK |
| Plate since | |
| | More info |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-03-29 |
| Last registration | 2024-02-22 |
| Complete history | See info |



| Registration #1 | 2018-03-29 | 11 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-03-10 | 15.139 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | 2022-02-25 | 18.811 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



BN18AXC report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 86% |
| Pedestrian | 65% |
| Safety systems | 81% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| Width | 1795 mm |
|---------------------|---------|
| Height | 1465 mm |
| Length | 4465 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1351 kg |
| Max. allowed weight | 1815 kg |

Additional information

| Fuel tank capacity | 51 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | PE 21129013 |

CarCheck.co.uk page 11/11