






report date: 2024-03-28

#### General information

Make	FORD	
Model	GALAXY TITANIUM TDCI	
Colour	Black	
Year of manufacture	2012	
Top speed	118 mph	
0 - 100 km/h	11.1 seconds	
Gearbox	6 speed automatic	

## Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28


## Internet history

#### Entry 2

Date 2023-12-12

Pictures 8









source: g3remarketing.co.uk

Entry 1

Date 2021-07-22

Pictures 65

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



BT12ZTF
report date: 2024-03-28

MOT history

MOT expiry date	2024-07-22
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	30
Total items failed	3

MOT #12		2023-07-01 08:27
MOT test numb	er	866634214987
Result		✓ Passed
Next expiry da	te	2024-07-22
<b>Advice</b> Item	s removed from driver's view prior to test	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush starting to deteriorate. (5.3.4 (a) (i))		

MOT #11	2022-07-16 08:25
MOT test number	119923608089
Result	✓ Passed

MOT #10	2021-07-23 14:07
MOT test number	255428363947
Result	<b>✓</b> Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



BT12ZTF
report date: 2024-03-28

MOT #9 2020-12-21 10:44

MOT test number 887631989148

**Result** ✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8** 2019-06-22 14:43

MOT test number 430944065838

Result \rightarrow Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #7 2019-06-22 14:42

**MOT test number** 558410532009

**Result** X Failed

**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #6** 2018-07-16 16:33

**MOT test number** 968273227192

**Result** 
✓ Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-07-16 10:08

MOT test number 933203398701

Result X Failed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**DANGEROUS** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #4 2017-07-07 15:21

MOT test number 485393620822

Result 

Passed

**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 5/13



Result

BT12ZTF
report date: 2024-03-28

✓ Passed

MOT #3 2017-07-07 10:32

MOT test number 127091704759

**Result** X Failed

**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2016-07-20 11:37

MOT test number 568146123682

Result 

Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2015-06-27 09:46

MOT test number 917458075110

**Notice** Under-trays fitted obscuring some underside components

**Notice** Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 6/13



BT12ZTF
report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	22 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



BT12ZTF report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
********		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-07-18
Last registration	2023-07-01
Complete history	See info



Registration #1	2012-07-18	8 mi
Registration #2	2015-06-27	21.054 mi
Registration #3	2016-07-20	27.821 mi
Registration #4	2017-07-07	36.641 mi
Registration #5	2017-07-07	36.641 mi
Registration #6	2018-07-16	46.587 mi
Registration #7	2018-07-16	46.588 mi
Registration #8		11.117 es
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		11.117 es
Registration #12		11.117 es
Registration #13		11.177 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2154 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1731 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13,

Number of axles2Engine numberCC09175