



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS EDGE TDCI
Colour	Silver
Year of manufacture	2014
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B








Internet history

Entry 2

Date	2021-09-04
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-25
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	34
Total items failed	23

MOT #19	2024-03-26 13:17
MOT test number	686028083227
Result	✓ Passed
Next expiry date	2025-03-25
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2024-03-12 11:18

MOT test number

323817146652

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #17

2023-09-06 12:11

MOT test number

511076126180

Result**✓ Passed**

**MOT #16**

2023-09-05 11:15

MOT test number

445595895839

Result**✗ Failed**

- Fail** Horn not working (7.7 (a))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Oil leaking excessively from transmission (8.4.1 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15

2023-03-10 10:29

MOT test number

625694335555

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14

2023-03-08 12:17

MOT test number

528042193635

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #13** 2022-09-09 12:26**MOT test number** 811184721380**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2022-09-07 11:19**MOT test number** 546661528858**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Rear Position lamp lens seriously defective (4.2.1 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2022-03-03 16:28**MOT test number** 433718220693**Result** ✓ Passed**MOT #10** 2022-03-03 12:16**MOT test number** 374403093991**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #9** 2021-09-13 15:10**MOT test number** 678740116578**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-09-08 16:16**MOT test number** 775026000056**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2021-09-07 13:56**MOT test number** 796089177334**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #6** 2021-01-16 00:00**MOT test number** 560079252105**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #5** 2021-01-16 00:00**MOT test number** 292183068230**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))**Pass with rectification** Bonnet cannot be secured in the closed position (3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #4** 2020-07-02 10:11**MOT test number** 324163066379**Result** ✓ Passed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MOT #3** 2019-07-18 08:35**MOT test number** 883642139354**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #2** 2018-08-20 07:32**MOT test number** 322000856738**Result** ✓ Passed



MOT #1	2017-08-24 11:50
MOT test number	517608407169
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
25 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	25 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BX64FWA
Plate since	2019-09-29
Current registration	BX64FWA
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2014-11-01
Last registration	2024-03-26
Complete history	See info



Registration #1	2014-11-01	23 mi
Registration #2	2017-08-24	60.554 mi
Registration #3	2018-08-20	83.275 mi
Registration #4	2019-07-18	97.597 mi
Registration #5	2020-07-02	108.802 mi
Registration #6	2021-01-16	114.003 mi
Registration #7	2021-01-16	114.003 mi
Registration #8	2021-09-07	126.497 mi
Registration #9	2021-09-08	126.497 mi
Registration #10	2021-09-13	126.723 mi
Registration #11	2021-09-13	126.723 mi
Registration #12	2021-09-13	126.723 mi
Registration #13	2021-09-13	126.723 mi
Registration #14	2021-09-13	126.723 mi
Registration #15	2021-09-13	126.723 mi
Registration #16	2021-09-13	126.723 mi
Registration #17	2021-09-13	126.723 mi
Registration #18	2021-09-13	126.723 mi
Registration #19	2021-09-13	126.723 mi
Registration #20	2021-09-13	126.723 mi
Registration #21	2021-09-13	126.723 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	82%
Pedestrian	72%
Safety systems	71%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1492 mm
Length	4560 mm
Wheel base	2648 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

