



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Silver
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-09-29
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-28
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-04
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	49
Total items failed	11

MOT #20	2023-10-05 06:38
MOT test number	917328143499
Result	✓ Passed
Next expiry date	2024-10-04
Advice	Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))

MOT #19	2023-10-02 09:20
MOT test number	846683673168
Result	✗ Failed
Fail	Nearside Front Steering rack has excessive free play detected at the steering wheel to the extent that safe steering is affected (steering rack fitted) Inner rack joint, excessive play (2.3 (a) (ii))
Fail	Front Headlamp has a product on the lens so that the light output is severely reduced Both sides (4.1.4 (b))
Advice	Rear Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))
Fail	Offside Front Steering rack has excessive free play detected at the steering wheel to the extent that safe steering is affected (steering rack fitted) inner rack joint, excessive play (2.3 (a) (ii))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Front Headlamp aim unable to be tested Both sides (4.1.2 (b))
Fail	Rear Exhaust silencer insecure (8.1.1 (b) (i))

**MOT #18**

2022-09-28 15:06

MOT test number

395692810340

Result

✓ Passed

Advice Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Brake disc worn, but not excessively Both sides (1.1.14 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Advice** Front Play in steering rack inner joint(s) Both sides**Advice** Front All direction indicators slightly discoloured Both sides (4.4.3 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Above the rear beam (1.1.11 (c))**Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))**MOT #17**

2022-09-28 07:54

MOT test number

884040985659

Result

✗ Failed

Advice Front Brake disc worn, but not excessively Both sides (1.1.14 (a) (i))**Advice** Front Play in steering rack inner joint(s) Both sides**Fail** Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Fail** Nearside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material Above the rear beam (1.1.11 (c))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front All direction indicators slightly discoloured Both sides (4.4.3 (a))**Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))**Advice** Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2021-09-29 10:46**MOT test number** 573371665687**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2021-01-29 13:10**MOT test number** 264293163361**Result** ✓ Passed**Advice** Under vehicle covered**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #14** 2020-02-11 13:30**MOT test number** 955039135750**Result** ✓ Passed**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Under cover trays/fitted**MOT #13** 2019-01-31 14:06**MOT test number** 718697362027**Result** ✓ Passed

**MOT #12** 2018-02-16 12:50**MOT test number** 723014816538**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2017-02-21 15:46**MOT test number** 862409580213**Result** ✓ Passed

- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #10 2016-02-25 18:02**MOT test number** 660108747683**Result** ✓ Passed**MOT #9** 2015-02-24 16:55**MOT test number** 559305455087**Result** ✓ Passed**MOT #8** 2014-02-11 07:17**MOT test number** 349872744035**Result** ✓ Passed

- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

**MOT #7** 2013-02-28 10:59**MOT test number** 156559953406**Result** ✓ Passed

- Notice** Rear exhaust silencer appears to be rattling at idle
- Notice** Under-trays fitted obscuring some underside components
- Notice** Front brake pads are getting low

MOT #6 2012-04-03 11:46**MOT test number** 178664892076**Result** ✓ Passed

- Notice** Slight corrosion on rear discs
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Both rear tyres perrishing

MOT #5 2011-04-05 14:51**MOT test number** 999645591072**Result** ✓ Passed

- Notice** Both rear tyres sidewalls starting to crack
- Notice** Offside rear and nearside rear tyres sidewalls starting to crack.

MOT #4 2011-03-28 12:27**MOT test number** 495777481026**Result** ✓ Passed

- Notice** Nearside rear tyre sidewalls starting to crack
- Notice** Offside rear tyre sidewalls starting to crack

**MOT #3** 2011-03-28 12:27**MOT test number** 238237681066**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)**Notice** Offside rear tyre sidewalls starting to crack**Pass with rectification** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Notice** Nearside rear tyre sidewalls starting to crack**MOT #2** 2010-04-06 12:05**MOT test number** 370286290065**Result** ✓ Passed**Notice** Rear tyres perishing**Notice** N/s front tyre perishing**Notice** Nail in offside rear tyre**MOT #1** 2009-08-12 10:50**MOT test number** 260174229278**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	PK56FKJ
Plate since	2024-03-29
Current registration	PK56FKJ
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	FINANCE
Date of agreement	2024-03-29	2024-03-29
Agreement type	RENAULT	FINANCE
Agreement term	RENAULT	FINANCE
Agreement number	RENAULT	FINANCE
Contact info	RENAULT	FINANCE

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-10-04
Last registration	2023-10-05
Complete history	See info



Registration #1	2006-10-04	6 mi
Registration #2	2009-08-12	4.005 mi
Registration #3	2010-04-06	4.534 mi
Registration #4	2011-03-28	39.845 mi
Registration #5	2011-04-05	11.237 mi
Registration #6	2012-04-03	19.424 mi
Registration #7	2013-02-28	22.694 mi
Registration #8	2014-02-11	26.137 mi
Registration #9	2015-02-24	29.143 mi
Registration #10	2016-02-25	31.547 mi
Registration #11	2017-02-21	34.803 mi
Registration #12	2018-02-21	38.059 mi
Registration #13	2019-02-21	41.315 mi
Registration #14	2020-02-21	44.571 mi
Registration #15	2021-02-21	47.827 mi
Registration #16	2022-02-21	51.083 mi
Registration #17	2023-02-21	54.339 mi
Registration #18	2024-02-21	57.595 mi
Registration #19	2025-02-21	60.851 mi
Registration #20	2026-02-21	64.107 mi
Registration #21	2027-02-21	67.363 mi
Registration #22	2028-02-21	70.619 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D089414