





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI TRENDLINE
Colour	White
Year of manufacture	2016
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 101 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history


Entry 1

Date 2021-10-05

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-06-05
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	8
Total items failed	5

MOT #9	2023-06-06 08:14
MOT test number	990098163670
Result	✓ Passed
Next expiry date	2024-06-05

MOT #8		2023-06-06 08:14
MOT test number		728239604649
Result		X Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	

MOT #7	2022-06-06 13:01
MOT test number	134911318935
Result	✓ Passed

MOT #6	2021-12-21 09:53
MOT test number	462957699157
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Offside Front Headlamp aim too low (4.1.2 (a))

Pass with rectification

Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #4

MOT test number

582315617501

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

939918565065

Result

Advice

Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

669040345223

Result

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Front Road wheel badly distorted (5.2.2 (c) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history

o which initially	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OR SIES
Plate since	
Current registration	AIR SIE
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-01-08
Last registration	2023-06-06
Complete history	See info



Registration #1	2016-01-08	11 mi
Registration #2	2019-01-08	46.977 mi
Registration #3	2019-01-09	46.978 mi
Registration #4	2020-01-09	61.867 mi
Registration #5	2021-01-11	71.591 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1823 mm
Length	4408 mm
Wheel base	2682 mm
Kerb weight	1478 kg
Max. allowed weight	2141 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	DFSD062212