



 **DA08ZYL**

report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L3H2 120 LWB HR PV
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-02
Pictures	3
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-24
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	30
Total items failed	11

MOT #20	2024-04-11 12:01
MOT test number	255479686053
Result	✓ Passed
Next expiry date	2025-04-24
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19	2024-04-10 07:55
MOT test number	640981637059
Result	✗ Failed
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
MAJOR	Offside Front Headlamp aim too low (4.1.2 (a))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
MAJOR	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Nearside Front Headlamp aim too low (4.1.2 (a))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Headlamp levelling device inoperative (4.1.5 (a))

**MOT #18** 2023-04-24 14:22**MOT test number** 708576625792**Result** ✓ Passed**Advice** Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))**Advice** Central Brake pipe corroded, covered in grease or other material unions corroded (1.1.11 (c))**MOT #17** 2023-04-21 10:03**MOT test number** 794882110307**Result** ✗ Failed**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Central Brake pipe corroded, covered in grease or other material unions corroded (1.1.11 (c))**Advice** Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))**MOT #16** 2022-04-25 08:59**MOT test number** 990217146799**Result** ✓ Passed**MOT #15** 2022-02-03 14:06**MOT test number** 901413326322**Result** ✓ Passed**MOT #14** 2021-04-01 13:20**MOT test number** 905533464216**Result** ✓ Passed

**MOT #13** 2019-06-28 07:48**MOT test number** 173184362069**Result** ✓ Passed**MOT #12** 2018-06-28 16:09**MOT test number** 911261138862**Result** ✓ Passed**MOT #11** 2017-06-24 11:37**MOT test number** 130767707932**Result** ✓ Passed**MOT #10** 2017-06-24 07:04**MOT test number** 568084776847**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9** 2016-05-23 14:22**MOT test number** 181991289994**Result** ✓ Passed**MOT #8** 2015-04-23 11:24**MOT test number** 948623615143**Result** ✓ Passed**MOT #7** 2015-04-22 17:32**MOT test number** 406092615100**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #6** 2014-07-31 09:53**MOT test number** 769502814255**Result** ✓ Passed**MOT #5** 2013-06-20 14:13**MOT test number** 387241573176**Result** ✓ Passed**MOT #4** 2013-06-13 10:07**MOT test number** 635844963141**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Notice** O/s outer sill has hole but not in prescribed area**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2012-07-02 12:56**MOT test number** 876774282117**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)

**MOT #2** 2012-06-28 09:26**MOT test number** 796060082129**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Rear Leaf spring has slight wear in a shackle pin and/or bush (2.4.B.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2011-06-23 11:16**MOT test number** 188194771189**Result** ✓ Passed

- Advice** Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 June
-------------------	--------------------

Days left	32
------------------	----

MOT expiry date	24 April 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-06-30
Last registration	2024-04-11
Complete history	See info



Registration #1	2008-06-30	23 mi
Registration #2	2011-06-23	34.569 mi
Registration #3	2012-06-28	52.148 mi
Registration #4	2012-07-02	52.435 mi
Registration #5	2013-06-13	62.690 mi
Registration #6	2013-06-20	63.042 mi
Registration #7	2014-07-31	74.044 mi
Registration #8	2015-04-22	82.462 mi
Registration #9	2015-04-23	82.462 mi
Registration #10	2016-05-23	85.629 mi
Registration #11	2017-06-24	86.201 mi
Registration #12	2018-06-20	86.201 mi
Registration #13	2019-06-20	86.201 mi
Registration #14	2020-06-20	86.201 mi
Registration #15	2021-06-20	86.201 mi
Registration #16	2022-06-20	86.201 mi
Registration #17	2023-06-20	86.201 mi
Registration #18	2024-06-20	86.201 mi
Registration #19	2025-06-20	86.201 mi
Registration #20	2026-06-20	86.201 mi
Registration #21	2027-06-20	86.201 mi
Registration #22	2028-06-20	86.201 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	1932 mm
Length	5413 mm
Kerb weight	1975 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20232357