



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 S S40
Colour	Red
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-30
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-07-30
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	23
Total items failed	14

MOT #20 2021-07-30 09:46**MOT test number** 671367948382**Result** ✓ Passed**Next expiry date** 2022-07-30

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

MOT #19 2021-07-29 13:44**MOT test number** 424436098521**Result** ✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

Fail Nearside Front Outer Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #18 2020-07-31 08:19**MOT test number** 381352263265**Result** ✓ Passed

**MOT #17** 2019-03-30 10:43**MOT test number** 234084573891**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm and inner tread uneven (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**MOT #16** 2019-03-29 11:09**MOT test number** 461805778343**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm and inner tread uneven (5.2.3 (e))**Fail** Offside Rear Anti-roll bar attachment bracket/mounting insecure (5.3.3 (a) (i))**Fail** Nearside Rear Anti-roll bar attachment bracket/mounting missing (5.3.3 (a) (ii))**MOT #15** 2018-05-29 15:22**MOT test number** 373599581602**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2018-05-26 09:06**MOT test number** 432597503961**Result** ✗ Failed**Fail** Front Registration plate inscription illegible (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13** 2017-04-24 10:55**MOT test number** 646481315420**Result** ✓ Passed**MOT #12** 2017-04-21 10:39**MOT test number** 153400990706**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Tyre tread depth below requirements of 1.6mm offside front (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #11** 2016-04-20 15:48**MOT test number** 361464792918**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2016-04-19 08:39**MOT test number** 662938209863**Result** ✗ Failed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Brake pad(s) wearing thin offside & nearside front (3.5.1g)**Advice** Direction indicator slightly discoloured offside & nearside rear (1.4.A.2f)**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #9** 2015-04-01 13:59**MOT test number** 316321195049**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-03-31 10:52**MOT test number** 625100895095**Result** ✗ Failed**Fail** Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside front tyre wearing on inner edge**MOT #7** 2014-04-19 13:27**MOT test number** 389449204182**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #6** 2013-04-23 11:27**MOT test number** 897773313194**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #5** 2012-04-21 13:15**MOT test number** 966382412188**Result** ✓ Passed**Notice** Child seat fitted to nearside rear not allowing full inspection of adult belt



MOT #4	2012-04-21 10:41
MOT test number	197252012191
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Child seat fitted to nearside rear not allowing full inspection of adult belt

MOT #3	2011-04-05 14:28
MOT test number	167505391001
Result	✓ Passed

MOT #2	2010-04-06 09:47
MOT test number	304836490027
Result	✓ Passed

MOT #1	2009-04-04 11:27
MOT test number	173354799491
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-03-30
Last registration	2021-07-30
Complete history	See info



Registration #1	2006-03-30	15 mi
Registration #2	2009-04-04	20.966 mi
Registration #3	2010-04-06	24.204 mi
Registration #4	2011-04-05	26.979 mi
Registration #5	2012-04-21	30.881 mi
Registration #6	2012-04-21	30.892 mi
Registration #7	2013-04-23	35.029 mi
Registration #8	2014-04-19	39.891 mi
Registration #9	2015-03-31	45.849 mi
Registration #10	2015-04-01	45.870 mi
Registration #11	2016-04-19	51.993 mi
Registration #12	2016-04-19	51.993 mi
Registration #13	2016-04-19	51.993 mi
Registration #14	2016-04-19	51.993 mi
Registration #15	2016-04-19	51.993 mi
Registration #16	2016-04-19	51.993 mi
Registration #17	2016-04-19	51.993 mi
Registration #18	2016-04-19	51.993 mi
Registration #19	2016-04-19	51.993 mi
Registration #20	2016-04-19	51.993 mi
Registration #21	2016-04-19	51.993 mi
Registration #22	2016-04-19	51.993 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number

56427