



HONDA



RJ100MF

report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA ES-T
Colour	Silver
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-07-14
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-11
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	33
Total items failed	5

MOT #12 2023-06-12 12:51

MOT test number 396793942444

Result ✓ Passed

Next expiry date 2024-06-11

**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**Minor** Rear Registration plate lamp throwing direct white light to the rear (4.7.1 (a))

MOT #11 2022-06-11 09:38

MOT test number 739372757530

Result ✓ Passed

**Advice** Play in steering rack inner joint(s)

**Advice** Headlamp has a product on the lens but not seriously reducing light output both front (4.1.4 (b))

**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Brake pad(s) wearing thin both front (1.1.13 (a) (ii))

**Advice** Tyre worn close to legal limit/worn on edge both rear, also cracked (5.2.3 (e))

**Advice** Vehicle structure has surface rust but structural rigidity is not significantly reduced

**MOT #10**

2021-04-09 10:18

**MOT test number**

856355784850

**Result**

✓ Passed

**Advice** Under-trays fitted obscuring some underside components**Advice** Front Headlamp has a product on the lens but not seriously reducing light output Nearside + Offside (4.1.4 (b))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9**

2021-03-29 14:45

**MOT test number**

333439969016

**Result**

✗ Failed

**Fail** Front Tyre has ply or cords exposed Nearside + Offside (5.2.3 (d) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output Nearside + Offside (4.1.4 (b))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Under-trays fitted obscuring some underside components**MOT #8**

2020-01-15 15:06

**MOT test number**

787978683568

**Result**

✓ Passed

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Tyre worn close to legal limit/worn on edge Nearside and Offside (5.2.3 (e))

**MOT #7** 2018-09-20 09:09**MOT test number** 558121222053**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6** 2017-06-02 13:48**MOT test number** 807953128397**Result** ✓ Passed**MOT #5** 2016-05-24 14:38**MOT test number** 488179102288**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2015-06-01 12:37**MOT test number** 948682155176**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #3	2015-06-01 12:37
MOT test number	467532255197
Result	✗ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #2	2014-05-28 12:15
MOT test number	536598344191
Result	✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #1	2013-05-28 12:59
MOT test number	725458143168
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
11 June 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	11 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 10,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-06-18
Last registration	2023-06-12
Complete history	<a href="#">See info</a>



Registration #1	2010-06-18	12 mi
Registration #2	2013-05-28	52.110 mi
Registration #3	2014-05-28	58.564 mi
Registration #4	2015-06-01	67.874 mi
Registration #5	2016-05-24	73.698 mi
Registration #6	2017-06-02	80.368 mi
Registration #7	2018-09-20	87.161 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2020-05-20	103.393 mi
Registration #10	2021-05-20	111.509 mi
Registration #11	2022-05-20	119.625 mi
Registration #12	2023-05-20	127.741 mi
Registration #13	2024-05-20	135.857 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 1072437