

Ford



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date Pictures 2021-09-24

30

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	58
Total items failed	1

MOT #15		2023-06-28 15:56
MOT test	number	492035990335
Result		✓ Passed
Next expi	ry date	2024-06-30
Advice	Nearside door mirror cover damaged	
Advice	Rear wiper blade split	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Offside Front day light running light damaged	
Advice	Nearside indicator repeater lamp damaged	
Advice	Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))	
Advice	Aux belt tensioner noisy	





MOT #14		2023-06-28 13:55
MOT test	number	694138711800
Result		🗙 Failed
MAJOR	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice	Aux belt tensioner noisy	
Advice	Nearside door mirror cover damaged	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
MAJOR	Offside Front Headlamp aim unable to be tested (4.1.2 (b))	
Advice	Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))	
Advice	Rear wiper blade split	
Advice	Offside Front day light running light damaged	
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Nearside indicator repeater lamp damaged	
DANGER	OUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR specified li	Exhaust emissions test not completed because smoke levels are significantly i mit values (8.2.2.2 (f))	n excess of the





MOT #13		2022-07-01 16:08
MOT test	number	247650358697
Result		✓ Passed
Advice	Offside Front day light running light damaged	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	



BT10LDV report date: 2024-03-29

MOT #12		2022-07-01 10:12
MOT test	number	342699943775
Result		🗙 Failed
MAJOR	Offside Side repeater incorrect colour (4.4.3 (a))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Offside Front day light running light damaged	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))	
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
MAJOR	Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR specified li	Exhaust emissions test not completed because smoke levels are significantly in imit values (8.2.2.2 (f))	excess of the

MOT #11		2021-06-03 14:55
MOT test	number	164255500963
Result		✓ Passed
Advice (5.2.3 (e))	Rear Tyre worn close to legal limit/worn on edge Both tyres are worn on i	inner & outer edges
Advice (5.2.3 (e))	Offside Front Tyre worn close to legal limit/worn on edge Tyre is worn on	inner & outer edges





MOT #10	2021-06-03 12:53
MOT test number	655387075981
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre is worn on (5.2.3 (e))	inner & outer edges
DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Rear Tyre worn close to legal limit/worn on edge Both tyres are worn on i (5.2.3 (e))	inner & outer edges
MOT #9	2020-08-19 13:30
MOT test number	418563803723

Result

МОТ #8	2019-05-20 12:33
MOT test number	246661159202
Result	✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view glass has small chip (3.2 (a) (i))

MOT #7		2019-05-20 12:33
MOT test number		335499158388
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	
Advice Offside Front Susarm bush (5.3.4 (a) (i))	spension arm pin or bush worn but not resulting in ex	cessive movement trailing
Minor Offside Front Windscreen damaged but not adversely affecting driver's view glass has small chip (3.2 (a) (i))		
Advice Nearside Rear Solarm bush (5.3.4 (a) (i))	uspension arm pin or bush worn but not resulting in e	excessive movement trailing

Passed





MOT #6	2018-05-22 14:07
MOT test number	559103570928
Result	✓ Passed
MOT #5	2017-05-31 11:38
MOT test number	717556814400
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
MOT #4	2016-05-11 09:55
MOT test number	183166194832
Result	✓ Passed
Advice Front brake discs corroded	

Advice Offside Front tyre worn on inner edge

Advice Nearside Rear child seat fitted

MOT #3	2015-06-01 11:32
MOT test number	417132455156
Result	✓ Passed
Notice Child seat is fitted	
MOT #2	2014 06 04 10:00
MOT #2	2014-06-04 10:00
MOT test number	915285054139
Result	Passed





MOT #1		2013-06-07 13:27
MOT test	number	526628053108
Result		✓ Passed
Notice	Middle row middle seat belt rubbing on the dog guard	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Both back row seats and seat belts not tested due to dog guard fitted	
Notice	Under-trays fitted obscuring some underside components	



Total payable by 12 monthly instalments

Tax & MOT check

✓ Taxed Tax due: 1 September 2024	MOT Expires: 30 June 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	30 June 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-

£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	 FE CO
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	C C C C
Date	
Category	 AMP
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-31
Last registration	2023-06-28
Complete history	See info



Registration #1	2010-07-31	27 mi
Registration #2	2013-06-07	7.238 mi
Registration #3	2014-06-04	15.998 mi
Registration #4	2015-06-01	27.712 mi
Registration #5	2016-05-11	37.842 mi
Registration #6	2017-05-31	52.232 mi
Registration #7	2018-05-22	65.294 mi
Registration #8	2019-05-20	80.265 mi
Registration #9	2019-05-20	80.265 mi
Registration #10		11.777 est
Registration #11		11.777 est
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est

More info \rightarrow





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 16/16

Engine number

AU21080