



S057KHC

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	Silver
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel





MOT history

MOT expiry date	2024-01-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	27
Total items failed	6

MOT #13	2023-01-30 13:22
MOT test number	520715594914
Result	✓ Passed
Next expiry date	2024-01-29
Advice	Service brake binding but not excessively rear both (1.2.1 (f))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12	2021-01-09 09:20
MOT test number	791578753714
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11	2020-01-08 12:37
MOT test number	758643266250
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2020-01-08 12:37**MOT test number** 505590585806**Result** ✗ Failed**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect re fit bulb (4.1.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-08-31 15:38**MOT test number** 327336389862**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2016-09-05 08:56**MOT test number** 807045367725**Result** ✓ Passed**MOT #7** 2016-09-05 08:56**MOT test number** 179513751379**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #6** 2015-06-24 11:35**MOT test number** 107345175144**Result** ✓ Passed**Notice** Nail in nearside rear tyre



MOT #5	2014-06-24 14:15
MOT test number	246355074134
Result	✓ Passed

MOT #4	2013-06-28 14:16
MOT test number	378469873115
Result	✓ Passed

- Notice

Bonnet safety catch sticks on occasionally
- Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice

Front brake disc's worn
- Notice

Rear brake disc's heavily worn with corrosion
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Notice

Exhaust balance weight broken,corroded

**MOT #3**

2013-06-26 10:45

MOT test number

565517073191

Result**✗ Failed****Fail**

Nearside Headlamp aim too low (1.8)

Notice

Items removed from driver's view prior to test

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Notice

Rear brake disc's heavily worn with corrosion

Notice

Exhaust balance weight broken,corroded

Pass with rectification

Offside Headlamp aim too low and too far to the right. (1.8)

Notice

Bonnet safety catch sticks on occasionally

Fail

Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)

Notice

Vehicle's internal headlight adjuster altered to recheck lights

Advice

Rear Brake pad(s) wearing thin (3.5.1g)

Notice

Front brake disc's worn

MOT #2

2011-12-13 09:31

MOT test number

848317341331

Result**✓ Passed****MOT #1**

2011-01-07 11:09

MOT test number

199307001400

Result**✓ Passed**



Tax & MOT check

✕
Untaxed

Tax expired:
19 February 2021

✕
MOT

Expired:
29 January 2024

Tax status	Expired at 19 February 2021
Days left	1164 days too late
MOT expiry date	29 January 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SO57KHC
Plate since	2019-03-28
Current registration	 SO57KHC
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-01-16
Last registration	2023-01-30
Complete history	See info



Registration #1	2008-01-16	15 mi
Registration #2	2011-01-07	37.006 mi
Registration #3	2011-12-13	47.567 mi
Registration #4	2013-06-26	54.899 mi
Registration #5	2013-06-28	54.918 mi
Registration #6	2014-06-24	56.887 mi
Registration #7	2015-06-24	65.245 mi
Registration #8	2016-06-24	73.603 mi
Registration #9	2017-06-24	81.961 mi
Registration #10	2018-06-24	90.319 mi
Registration #11	2019-06-24	98.677 mi
Registration #12	2020-06-24	107.035 mi
Registration #13	2021-06-24	115.393 mi
Registration #14	2023-01-30	123.751 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Kerb weight	1416 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	BLS 896160