



General information

Make	FIAT
Model	500L MULTIJET TREKKING DUALOGIC
Colour	Beige
Year of manufacture	2015
Top speed	98 mph
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-01-22
Pictures	13
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-05-03
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	6

MOT #9	2024-04-05 15:30
MOT test number	588449602981
Result	✓ Passed
Next expiry date	2025-05-03

MOT #8	2023-04-25 09:33
MOT test number	176013461409
Result	✓ Passed

MOT #7	2022-05-04 12:18
MOT test number	985960353271
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6** 2022-04-27 08:26**MOT test number** 840831542887**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2021-05-04 09:08**MOT test number** 955887442006**Result** ✓ Passed**MOT #4** 2020-02-19 16:42**MOT test number** 264348936229**Result** ✓ Passed**MOT #3** 2020-02-17 11:16**MOT test number** 806784121036**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively x2 (3.4 (b) (ii))**Fail** Offside Front Tyre not fitted in accordance with side wall instructions rotation (5.2.3 (i))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))



MOT #2	2019-03-07 14:22
MOT test number	736264720656
Result	✓ Passed
MOT #1	2018-06-11 15:17
MOT test number	336057668288
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
3 May 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	3 May 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-07-06
Last registration	2024-04-05
Complete history	See info



Registration #1	2015-07-06	21 mi
Registration #2	2018-06-11	46.277 mi
Registration #3	2019-03-07	49.515 mi
Registration #4	2020-02-17	52.599 mi
Registration #5	2020-02-19	52.599 mi
Registration #6	2020-03-20	55.277 mi
Registration #7	2020-04-20	55.277 mi
Registration #8	2020-05-20	55.277 mi
Registration #9	2020-06-20	55.277 mi
Registration #10	2020-07-20	55.277 mi
Registration #11	2020-08-20	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2018 mm
Height	1679 mm
Length	4270 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5754585