





report date: 2024-03-29

General information

Make	FORD
Model	B-MAX TITANIUM
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 118 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-27


Pictures 13

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-22
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #11	2023-08-17 12:00
MOT test number	158950052973
Result	✓ Passed
Next expiry date	2024-08-22
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10		2023-08-16 10:55
MOT test	number	428433817468
Result		× Failed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice the offside	Front Brake pads are fitted incorrectly two inner pads on the nearside front front. Brake efficiency ok	t and two outer pads on
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Nail in tyre	
Fail Er	ngine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Central Rear Engine mounting damaged but not to excess dog leg (6.1.8 (a) (i))

MOT #8 2022-08-05 08:50 **MOT** test number 299476913037 Result × Failed Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i)) **Advice** Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

 MOT #7
 2021-08-17 14:47

 MOT test number
 255856554876

 Result
 ✓ Passed

MOT #6 2020-06-16 15:49
MOT test number 607770464773

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on outside edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4 2018-06-13 15:42

MOT test number 929143807382

MOT #3 2018-06-13 08:48

MOT test number 918776745288

Result X Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #2 2017-06-14 10:53

MOT test number 347784807884

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-06-07 12:00

MOT test number 939304946535

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner I	nistory
---------	---------

,	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-28
Last registration	2023-08-17
Complete history	See info



Registration #1	2013-06-28	8 mi
Registration #2	2016-06-07	25.318 mi
Registration #3	2017-06-14	34.753 mi
Registration #4	2018-06-13	42.099 mi
Registration #5	2018-06-13	42.099 mi
Registration #6	2019-06-13	48.701 mi
Registration #7	2020-06-16	53.957 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 44
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		10.377 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

Engine number DK03316