



GYIOWPA

report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Silver
Year of manufacture	2010
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2024-06-14
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	13
Total items failed	4

MOT #16	2023-06-15 12:59
MOT test number	300042716117
Result	✓ Passed
Next expiry date	2024-06-14

MOT #15	2022-07-20 10:11
MOT test number	500708700843
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14	2022-07-20 10:11
MOT test number	392699039796
Result	✗ Failed
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #13	2021-07-14 17:28
MOT test number	112346410323
Result	✓ Passed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-07-14 10:07**MOT test number** 361090745065**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #11** 2020-06-29 16:19**MOT test number** 597218939290**Result** ✓ Passed**MOT #10** 2020-06-29 14:39**MOT test number** 652028713934**Result** ✗ Failed**Fail** Central Rear Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**MOT #9** 2019-06-27 12:38**MOT test number** 620819800365**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2019-06-27 09:36**MOT test number** 474201493246**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm 155/65x14 (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2018-07-12 11:02**MOT test number** 537884003633**Result** ✓ Passed**MOT #6** 2017-07-25 15:27**MOT test number** 261577860473**Result** ✓ Passed**MOT #5** 2016-07-27 11:50**MOT test number** 412243668651**Result** ✓ Passed**MOT #4** 2015-08-26 00:00**MOT test number** 701362721784**Result** ✓ Passed**MOT #3** 2014-09-04 13:15**MOT test number** 987417044231**Result** ✓ Passed



MOT #2	2013-09-30 11:01
MOT test number	726223873224
Result	✓ Passed

MOT #1	2013-07-08 10:31
MOT test number	646289883110
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
14 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-10
Last registration	2023-06-15
Complete history	See info



Registration #1	2010-07-10	29 mi
Registration #2	2013-07-08	12.034 mi
Registration #3	2013-09-30	12.739 mi
Registration #4	2014-09-04	15.055 mi
Registration #5	2015-08-26	17.271 mi
Registration #6	2016-07-27	19.535 mi
Registration #7	2017-07-25	20.923 mi
Registration #8	2018-07-12	30.509 mi
Registration #9	2019-06-27	39.057 mi
Registration #10	2020-06-27	45.377 mi
Registration #11	2021-06-27	51.697 mi
Registration #12	2022-06-27	58.017 mi
Registration #13	2023-06-27	64.337 mi
Registration #14	2024-06-27	70.657 mi
Registration #15	2025-06-27	76.977 mi
Registration #16	2026-06-27	83.297 mi
Registration #17	2027-06-27	89.617 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1124148