



RENAULT

HY6IPOU


report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA DYNAMIQUE TOMTOM DCI FAP
Colour	Black
Year of manufacture	2011
Top speed	131 mph
0 - 100 km/h	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 150 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.6 mpg
Consumption extra urban	53.5 mpg
Consumption combined	45.2 mpg
CO2 emission	136 g/km
CO2 label	E






Internet history

Entry 1

Date	2022-07-22
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-10
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	32
Total items failed	7

MOT #13	2023-07-11 14:25
MOT test number	180666523610
Result	✓ Passed
Next expiry date	2024-07-10

MOT #12	2021-08-25 12:37
MOT test number	165134448141
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2021-08-24 11:53

MOT test number

656030611332

Result**✗ Failed**

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10

2020-08-27 12:34

MOT test number

929880666228

Result**✓ Passed**

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Undertrays fitted

MOT #9

2020-08-26 15:45

MOT test number

336161681906

Result**✗ Failed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Brake performance not tested (1.2.1 (g))
- Advice** Undertrays fitted
- Fail** Brake pipe leaking on an air braking system covered by plastic undertray (1.1.11 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #8	2019-08-16 16:11
MOT test number	980831212527
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7	2019-08-16 10:33
MOT test number	698534443358
Result	✗ Failed
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #6	2018-09-03 09:32
MOT test number	240333371941
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT #5	2017-08-21 13:49
MOT test number	393519116765
Result	✓ Passed
Advice	Undertrays fitted not allowing full inspection of underside components
Advice	Covers fitted not allowing full inspection of engine bay components
Advice	Child seat(s) fitted not allowing full inspection of adult seatbelts
Advice	Opacity 0.03

**MOT #4** 2017-08-21 10:45**MOT test number** 701494222995**Result** ✗ Failed**Advice** Covers fitted not allowing full inspection of engine bay components**Advice** Child seat(s) fitted not allowing full inspection of adult seatbelts**Advice** Opacity 0.03**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Undertrays fitted not allowing full inspection of underside components**MOT #3** 2016-08-22 14:21**MOT test number** 825458972215**Result** ✓ Passed**Advice** Opacity 0.00 @ 5.500 rpm**Advice** Covers fitted not allowing full inspection**MOT #2** 2015-08-24 08:45**MOT test number** 234488577512**Result** ✓ Passed**Advice** Under trays fitted not allowing full inspection of items**Advice** Engine covers fitted not allowing full inspection of items**MOT #1** 2014-09-02 13:36**MOT test number** 367175244290**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 July 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	HY61POU
Plate since	2019-03-29
Current registration	HY61POU
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT
Date of agreement	2024-03-29
Agreement type	RENAULT
Agreement term	RENAULT
Agreement number	RENAULT
Contact info	RENAULT

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-01
Last registration	2023-07-11
Complete history	See info



Registration #1	2011-09-01	25 mi
Registration #2	2014-09-02	38.800 mi
Registration #3	2015-08-24	46.920 mi
Registration #4	2016-08-22	55.203 mi
Registration #5	2017-08-21	65.354 mi
Registration #6	2017-08-21	65.354 mi
Registration #7	2018-09-03	73.689 mi
Registration #8	2019-08-16	81.981 mi
Registration #9	2020-08-20	90.272 mi
Registration #10	2021-08-19	98.563 mi
Registration #11	2022-08-18	106.854 mi
Registration #12	2023-07-11	115.145 mi
Registration #13	2023-07-11	115.145 mi
Registration #14	2023-07-11	115.145 mi
Registration #15	2023-07-11	115.145 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2060 mm
Height	1445 mm
Length	4803 mm
Wheel base	2758 mm
Kerb weight	1492 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	C016506