



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Silver
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-01
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-27
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	26
Total items failed	17

MOT #22 2023-05-25 10:35

MOT test number 588983700123

Result ✓ Passed

Next expiry date 2024-05-27

- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Nail in tyre

MOT #21 2023-05-25 10:35

MOT test number 844342206742

Result ✗ Failed

- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Nail in tyre
- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



MOT #20 2022-05-25 10:26

MOT test number 282906657447

Result ✔ Passed

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))

Advice Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both sides (6.1.1 (c) (i))

MOT #19 2021-05-28 11:59

MOT test number 240021092174

Result ✔ Passed

MOT #18 2021-05-28 09:24

MOT test number 616608890587

Result ✘ Failed

Fail Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))



MOT #17	2020-03-27 10:39
MOT test number	276306292144
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2020-03-27 10:39
MOT test number	345270457845
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2019-05-01 14:20
MOT test number	647459132791
Result	✓ Passed

MOT #14	2018-03-30 20:22
MOT test number	918990376213
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #13	2017-04-24 09:03
MOT test number	793698513522
Result	✓ Passed



MOT #12	2017-04-07 12:52
MOT test number	207329151211
Result	✗ Failed
Fail	Exhaust engine idle speed too high (7.3.D.1)
Fail	Nearside Rear Stop lamp not working (1.2.1b)

MOT #11	2016-04-11 13:05
MOT test number	517186427735
Result	✓ Passed
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
Advice	Offside Front tyre outer edge slightly worn
Advice	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Front tyre outer edge slightly worn
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #10	2015-04-27 13:02
MOT test number	296417115149
Result	✓ Passed

MOT #9	2014-04-07 12:18
MOT test number	675627994052
Result	✓ Passed

MOT #8	2013-04-04 12:52
MOT test number	277984993022
Result	✓ Passed



MOT #7 2012-04-03 13:17

MOT test number 509024792073

Result ✓ Passed

MOT #6 2011-06-21 08:59

MOT test number 787382871131

Result ✓ Passed

MOT #5 2011-04-28 15:35

MOT test number 275368111189

Result ✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

MOT #4 2011-04-28 15:35

MOT test number 545208611181

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2010-05-05 15:17

MOT test number 244085820470

Result ✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2009-05-06 15:14
MOT test number	122196729122
Result	✓ Passed
Notice	Scratches on screen zone a
Notice	N/s/f & o/s/f door check straps brocken

MOT #1	2008-05-02 11:29
MOT test number	240913928497
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
27 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GV05BVU
Plate since	2023-03-28
Current registration	GV05BVU
Plate since	2023-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-04-30
Last registration	2023-05-25
Complete history	See info



Registration #1	2005-04-30	26 mi
Registration #2	2008-05-02	26.057 mi
Registration #3	2009-05-06	36.823 mi
Registration #4	2010-05-05	47.987 mi
Registration #5	2011-04-28	53.524 mi
Registration #6	2011-06-21	53.885 mi
Registration #7	2012-04-03	57.522 mi
Registration #8	2013-04-04	63.338 mi
Registration #9	2014-04-07	67.716 mi
Registration #10	2015-04-27	73.173 mi
Registration #11	2016-04-11	76.553 mi
Registration #12	2017-04-07	83.186 mi
Registration #13	2018-05-02	83.186 mi
Registration #14	2019-05-06	83.186 mi
Registration #15	2020-05-05	83.186 mi
Registration #16	2021-04-28	83.186 mi
Registration #17	2021-06-21	83.186 mi
Registration #18	2022-04-03	83.186 mi
Registration #19	2023-04-04	83.186 mi
Registration #20	2023-04-07	83.186 mi
Registration #21	2023-04-27	83.186 mi
Registration #22	2023-04-11	83.186 mi
Registration #23	2023-04-07	83.186 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

4ZZU640926