





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI SPORT 5 STR
Colour	Black
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-24

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT #11		2021-06-12 11:47
MOT test	number	517693855450
Result		✓ Passed
Next expi	ry date	2022-06-11
Advice	Offside Front tyre worn om inner edge	
Advice	Offside Rear tyre wearing on inner edge	

MOT #10		2020-02-14 14:39
MOT test	number	115944315609
Result		✓ Passed
MOT #9		2019-02-26 14:41
MOT test	number	884622006693
Result		✓ Passed
Advice	Engine covers fitted	
Advice	Under travs fitted not allowing inspection of some underside components	

MOT #8	2018-03-07 17:01
MOT test number	667317521813
Result	✓ Passed
Advice Offside Rear brake disc worn, pitted or scored, but not seriously weaker braking surface (3.5.1i)	ned Pad not using full

MOT #7	2018-03-06 11:51
MOT test number	827119852490
Result	× Failed

CarCheck.co.uk page 3/11

Fail	Driver's door cannot be opened from inside the vehicle (6.2.B.1b)
Fail	Offside Headlamp aim too far to the left (1.8)
Fail	Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)
Advi o	Offside Rear brake disc worn, pitted or scored, but not seriously weakened Pad not using full g surface (3.5.1i)



Fail

Fail

DS09DFV

report date: 2024-03-29

MOT #6	2016-07-01 13:10
MOT test number	508845057277
Result	✓ Passed
MOT #5	2015-08-10 16:48
MOT test number	575932525218
Result	✓ Passed
MOT #4	2015-08-10 14:44
MOT test number	428632125294
Result	X Failed

Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #3		2014-08-06 10:22
MOT test	number	365118214252
Result		✓ Passed
MOT #2		2013-08-08 09:17
MOT test	number	318130623465
Result		✓ Passed
Notice	Nail in offside rear tyre	
Advice	Rear brake fluctuating, but not excessively (3.7.B.3)	
Notice	Both rear tyres heavily cracked on inner edges	
Advice	Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #1		2012-07-07 10:47
MOT test	number	479549882132
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Rear tyres wearing on inner edges	

CarCheck.co.uk page 5/11




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

owner mistery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

THE REAL PROPERTY OF THE PERTY	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-07-15
Last registration	2021-06-12
Complete history	See info



Registration #1	2009-07-15	29 mi
Registration #2	2012-07-07	38.616 mi
Registration #3	2013-08-08	56.583 mi
Registration #4	2014-08-06	60.640 mi
Registration #5	2015-08-10	64.935 mi
Registration #6	2015-08-10	64.935 mi
Registration #7	2016-07-01	68.349 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaelesande	maga 11/11

CarCheck.co.uk page 11/11

Number of seats	7
Engine number	BKD C72007