




report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE D XS
Colour	Blue
Year of manufacture	2007
Top speed	143 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-10-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-10-27
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	9

MOT #17 2021-10-28 15:02

MOT test number 890614673374

Result ✓ Passed

Next expiry date 2022-10-27

**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2021-10-26 13:07

MOT test number 936794283935

Result ✗ Failed

**Fail** Nearside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Central Front Registration plate inscription illegible (0.1 (b))

**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

**Fail** Offside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #15** 2021-03-16 09:59**MOT test number** 457090597084**Result** ✓ Passed**MOT #14** 2020-03-17 10:06**MOT test number** 904379704872**Result** ✓ Passed**MOT #13** 2019-02-19 10:59**MOT test number** 173629789185**Result** ✓ Passed**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12** 2019-02-19 10:59**MOT test number** 402275210441**Result** ✗ Failed**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #11** 2018-02-19 10:13**MOT test number** 706975996716**Result** ✓ Passed**MOT #10** 2017-02-28 14:37**MOT test number** 219741469120**Result** ✓ Passed**Advice** Front tyres wearing inner edges



<b>MOT #9</b>	2016-02-26 12:39
---------------	------------------

<b>MOT test number</b>	247831188468
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2015-03-19 16:18
---------------	------------------

<b>MOT test number</b>	598858975066
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2015-02-20 11:53
---------------	------------------

<b>MOT test number</b>	736481855003
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

**Fail** Brake operation has insufficient reserve pressure/vacuum to provide assistance for at least two more brake applications after the warning lamp or other device has operated (3.3.E.5b)

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #6</b>	2014-02-19 12:10
---------------	------------------

<b>MOT test number</b>	256640454035
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2013-03-14 13:00
---------------	------------------

<b>MOT test number</b>	879043973066
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**MOT #4** 2013-02-26 11:56**MOT test number** 277327053088**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nearside rear inside edge wearing
- Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Offside front tyre wearing inside edge
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #3** 2012-02-21 11:04**MOT test number** 295772952079**Result** ✓ Passed**MOT #2** 2012-02-21 08:35**MOT test number** 685262352029**Result** ✗ Failed

- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #1** 2011-01-28 09:58**MOT test number** 106258121402**Result** ✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>EF57XYL</b>
Plate since	2024-03-29
Current registration	<b>EF57XYL</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-30
Last registration	2021-10-28
Complete history	<a href="#">See info</a>



Registration #1	2007-11-30	18 mi
Registration #2	2011-01-28	39.117 mi
Registration #3	2012-02-21	44.300 mi
Registration #4	2012-02-21	44.300 mi
Registration #5	2013-02-26	49.980 mi
Registration #6	2013-03-14	50.161 mi
Registration #7	2014-02-19	54.626 mi
Registration #8	2015-02-20	60.528 mi
Registration #9	2015-03-19	60.772 mi
Registration #10	2016-02-26	65.501 mi
Registration #11	2016-03-20	65.501 mi
Registration #12	2016-03-20	65.501 mi
Registration #13	2016-03-20	65.501 mi
Registration #14	2016-03-20	65.501 mi
Registration #15	2016-03-20	65.501 mi
Registration #16	2016-03-20	65.501 mi
Registration #17	2016-03-20	65.501 mi
Registration #18	2016-03-20	65.501 mi
Registration #19	2016-03-20	65.501 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	02224317G