



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XE
Colour	Blue
Year of manufacture	2003
Top speed	106 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	313 Nm at 2.500 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-30
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-06-02
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	50
Total items failed	23

MOT #23	2021-05-27 15:03
MOT test number	868299030597
Result	✓ Passed
Next expiry date	2022-06-02
Advice	Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #22**

2021-05-24 11:29

**MOT test number**

319448013658

**Result**

✗ Failed

- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Inner Tyre slightly damaged/cracking or perishing center (5.2.3 (d) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Rear Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Inner Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Nearside Rear Inner Brake pipe excessively damaged (1.1.11 (c))

**MOT #21**

2020-06-03 14:24

**MOT test number**

193229761804

**Result**

✓ Passed

- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sill (6.1.1 (c) (i))
- Advice** Front number plate cracked but can still be read
- Advice** Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))

**MOT #20**

2020-05-28 09:39

**MOT test number**

507334005791

**Result****✗ Failed**

- Advice** Front number plate cracked but can still be read
- Fail** Brake cable insecure rear bolt snapped (1.1.15 (c))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced inner sill (6.1.1 (c) (i))
- Advice** Brake pipe corroded, covered in grease or other material all rear (1.1.11 (c))
- Fail** Headlamp light intensity severely reduced both front (4.1.4 (a))
- Fail** Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Rear Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Fail** Offside Front Anti-roll bar pin or bush excessively worn D bush (5.3.4 (a) (i))
- Fail** Offside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced next to spring mount (6.1.1 (c) (i))

**MOT #19**

2019-05-17 12:07

**MOT test number**

649158733176

**Result****✓ Passed**

- Advice** Rear chassis rail slightly rusty
- Advice** Front brake pads getting low
- Advice** Both headlight lens cloudy
- Advice** Offside rear inner sill rusty

**MOT #18** 2019-05-17 08:12**MOT test number** 621649773546**Result** ✗ Failed**Advice** Rear chassis rail slightly rusty**Advice** Front brake pads getting low**Advice** Both headlight lens cloudy**Advice** Offside rear inner sill rusty**Fail** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**MOT #17** 2018-05-23 14:26**MOT test number** 893223486373**Result** ✓ Passed**Advice** Rear chassis cross member slightly corroded**MOT #16** 2017-05-24 09:16**MOT test number** 876573305866**Result** ✓ Passed**MOT #15** 2017-05-24 08:03**MOT test number** 789141357601**Result** ✗ Failed**Fail** Nearside rear brake recording little or no effort hand brake (3.7.B.5a)**Fail** Offside Rear Panhard rod rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #14** 2016-05-18 16:57**MOT test number** 475718817240**Result** ✓ Passed

**MOT #13** 2015-05-27 08:55**MOT test number** 559457745128**Result** ✓ Passed**MOT #12** 2015-01-26 15:14**MOT test number** 195246325090**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** Spare tyre defective**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Limited movement n/s/r park cable/linkage**MOT #11** 2015-01-23 17:07**MOT test number** 636513225090**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Spare tyre defective**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #10**

2014-01-20 17:52

**MOT test number**

495670424056

**Result**

✓ Passed

- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Front to rear brake pipes,both,at rear some of which are under plastic coating unable to fully check, advise further investigation
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight bind n/s/r brake
- Advice** Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #9**

2014-01-17 15:22

**MOT test number**

997347414002

**Result**

✗ Failed

- Advice** Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Notice** Slight bind n/s/r brake
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Front to rear brake pipes,both,at rear some of which are under plastic coating unable to fully check, advise further investigation
- Fail** Braking system leaking (3.6.A.1)



**MOT #8** 2013-01-21 13:52**MOT test number** 618601323080**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Both sides rear tyres wearing on inner edges**Advice** Nearside Rear Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2012-01-09 15:51**MOT test number** 157489102041**Result** ✓ Passed**Notice** Oil leak**MOT #6** 2011-01-04 11:19**MOT test number** 239574801038**Result** ✓ Passed**MOT #5** 2010-01-22 13:12**MOT test number** 500742920036**Result** ✓ Passed**MOT #4** 2009-01-20 15:26**MOT test number** 741450229062**Result** ✓ Passed**Notice** Front brake pads low**MOT #3** 2008-01-28 14:08**MOT test number** 682908328033**Result** ✓ Passed



MOT #2	2008-01-28 10:17
MOT test number	484768328022
Result	✗ Failed
<div>Fail</div> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #1	2007-01-03 13:05
MOT test number	211243207008
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 September 2022

X

MOT

Expired:  
2 June 2022

Tax status	Expired at 1 September
Days left	607 days too late
MOT expiry date	2 June 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-12-10
Last registration	2021-05-27
Complete history	<a href="#">See info</a>



Registration #1	2003-12-10	21 mi
Registration #2	2007-01-03	32.849 mi
Registration #3	2008-01-28	41.528 mi
Registration #4	2008-01-28	41.528 mi
Registration #5	2009-01-20	51.620 mi
Registration #6	2010-01-22	55.810 mi
Registration #7	2011-01-04	60.462 mi
Registration #8	2012-01-09	65.136 mi
Registration #9	2013-01-21	69.100 mi
Registration #10	2014-01-17	78.177 mi
Registration #11	2014-01-20	78.232 mi
Registration #12	2015-01-23	88.919 mi
Registration #13	2015-01-26	88.997 mi
Registration #14	2015-01-26	88.997 mi
Registration #15	2015-01-26	88.997 mi
Registration #16	2015-01-26	88.997 mi
Registration #17	2015-01-26	88.997 mi
Registration #18	2015-01-26	88.997 mi
Registration #19	2015-01-26	88.997 mi
Registration #20	2015-01-26	88.997 mi
Registration #21	2015-01-26	88.997 mi
Registration #22	2015-01-26	88.997 mi
Registration #23	2015-01-26	88.997 mi
Registration #24	2015-01-26	88.997 mi
Registration #25	2015-01-26	88.997 mi





Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	D4CB3590642