





report date: 2024-03-29

General information

Make	FORD
Model	KUGA ZETEC TDCI
Colour	Grey
Year of manufacture	2015
Top speed	118 mph
0 - 100 km/h	10.0 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	132 kW / 180 HP / 148 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-29


Internet history


Entry 2


Date 2023-01-13


Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-14

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-30
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #8	2023-10-31 12:17
MOT test number	336334244978
Result	✓ Passed
Next expiry date	2024-10-30

MOT #7	2022-12-09 15:07	
MOT test i	number 582795006471	
Result	✓ Passed	
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin just above pass value (recommend replacement) (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Nail in tyre	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Engine covers and under trays fitted	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2022-12-06 12:49 **MOT** test number 680789664776 Result **X** Failed **Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Front Nail in tyre **MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Front Brake pad(s) wearing thin just above pass value (recommend replacement) (1.1.13 (a) (ii)) Advice Engine covers and under trays fitted Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #5	2021-10-02 08:21
MOT test number	707498113860
Result	✓ Passed

MOT #4 2021-09-20 15:51
MOT test number 893774527552

Result × Failed

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3	2021-02-01 15:07
MOT test number	478598111206
Result	✓ Passed
Advice Nearside Rear Nail in tyre	

ricarsiae ricar riam in cyre	
MOT #2	2019-09-19 12:07
MOT test number	329464966434
Result	✓ Passed
MOT #1	2018-09-25 11:43
MOT test number	414719252373
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner his	ttorv

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



SM65UVL report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-11-26
Last registration	2023-10-31
Complete history	See info



Registration #1	2015-11-26	16 mi
Registration #2	2018-09-25	11.915 mi
Registration #3	2019-09-19	17.286 mi
Registration #4	2021-02-01	31.821 mi
Registration #5		11.777 es
Registration #6	2021-09-20	38.639 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	86%
Pedestrian	70%
Safety systems	100%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	2077 mm
Height	1703 mm
Length	4524 mm
Wheel base	2690 mm
Kerb weight	1616 kg
Max. allowed weight	2230 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/1