



report date: 2024-03-29

General information

Make	CITROEN
Model	C3 PICASSO BLUEHDI EDITION PICASSO
Colour	Purple
Year of manufacture	2016
Top speed	111 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	B








Internet history

Entry 4

Date	2021-10-16
Pictures	35
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 3

Date	2021-10-16
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

Entry 2

Date	2021-10-03
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-02
Pictures	0
Listing price	<a href="#">View report</a>

source: [heyicar.co.uk](#)



## MOT history

MOT expiry date	2024-11-03
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	17
Total items failed	2

## MOT #7 2023-10-13 14:44

MOT test number 163752631958

Result ✓ Passed

Next expiry date 2024-11-03

**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Exhaust mounting defective (6.1.2 (a))

## MOT #6 2022-11-03 16:34

MOT test number 276873441912

Result ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #5** 2022-11-02 13:10**MOT test number** 151588542032**Result** ✗ Failed**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2021-11-04 10:00**MOT test number** 215986820289**Result** ✓ Passed**MOT #3** 2020-12-17 09:52**MOT test number** 796176723590**Result** ✓ Passed**MOT #2** 2020-01-03 11:45**MOT test number** 457949434177**Result** ✓ Passed



MOT #12019-09-03 10:53

MOT test number156214952906

Result

✓ Passed

- Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))
- Advice

TPS light on
- Advice

Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
3 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	3 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-10-24
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2016-10-24	21 mi
Registration #2	2019-09-03	9.959 mi
Registration #3	2020-01-03	10.835 mi
Registration #4	2020-12-17	24.041 mi
Registration #5	2023-10-13	25.277 mi
Registration #6	2023-10-13	25.277 mi
Registration #7	2023-10-13	25.277 mi
Registration #8	2023-10-13	25.277 mi
Registration #9	2023-10-13	25.277 mi
Registration #10	2023-10-13	25.277 mi
Registration #11	2023-10-13	25.277 mi
Registration #12	2023-10-13	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHA3137763