



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-01-08
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-03-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	21
Total items failed	7

MOT #13	2023-03-08 17:15
MOT test number	666689543377
Result	✓ Passed
Next expiry date	2024-03-07
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12	2022-03-08 16:51
MOT test number	984814949549
Result	✓ Passed
Advice	Vehicle has been under sealed

MOT #11	2022-03-05 12:54
MOT test number	448427534289
Result	✗ Failed
Advice	Vehicle has been under sealed
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #10** 2021-09-21 16:55**MOT test number** 348577138507**Result** ✓ Passed**Advice** Under side of vehicle heavily corroded**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #9** 2020-08-13 12:39**MOT test number** 255219777975**Result** ✓ Passed**MOT #8** 2019-08-21 13:08**MOT test number** 432112424676**Result** ✓ Passed**MOT #7** 2019-02-20 10:22**MOT test number** 261748635918**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing N/S & O/S Front and Rear tyre's (5.2.3 (d) (ii))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S Rear Disc's (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S Front Disc's (1.1.14 (a) (ii))**Advice** Engine has slight oil leak

**MOT #6** 2019-02-20 10:22**MOT test number** 313878961804**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S Rear Disc's (1.1.14 (a) (ii))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine has slight oil leak**Advice** Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S Front Disc's (1.1.14 (a) (ii))**Pass with rectification** Rear Reversing lamp inoperative (4.6.1 (a))**Advice** Tyre slightly damaged/cracking or perishing N/S & O/S Front and Rear tyre's (5.2.3 (d) (ii))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #5** 2018-02-23 15:27**MOT test number** 620128363652**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2018-02-22 13:16**MOT test number** 385660200639**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #3	2017-02-23 16:23
---------------	------------------

MOT test number	431859189604
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2016-03-26 09:24
---------------	------------------

MOT test number	620389737454
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear tyre cracking on side wall
---------------	--

MOT #1	2016-03-26 09:24
---------------	------------------

MOT test number	270435611861
------------------------	--------------

Result	✗ Failed
---------------	----------

Advice	Nearside Rear tyre cracking on side wall
---------------	--

Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
--------------------------------	--



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SK62FCZ
Plate since	2019-03-28
Current registration	 SK62FCZ
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-01-31
Last registration	2023-03-08
Complete history	See info



Registration #1	2013-01-31	25 mi
Registration #2	2016-03-26	19.172 mi
Registration #3	2016-03-26	19.172 mi
Registration #4	2017-02-23	22.430 mi
Registration #5	2018-02-22	41.314 mi
Registration #6	2018-02-23	41.313 mi
Registration #7	2019-02-20	56.571 mi
Registration #8	2019-02-20	56.571 mi
Registration #9	2019-03-20	56.571 mi
Registration #10	2019-03-20	56.571 mi
Registration #11	2019-03-20	56.571 mi
Registration #12	2019-03-20	56.571 mi
Registration #13	2019-03-20	56.571 mi
Registration #14	2019-03-20	56.571 mi
Registration #15	2019-03-20	56.571 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K