





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Red
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1


Date 2021-06-10


Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-05
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	4

MOT #13	2023-07-03 13:45
MOT test number	941716258872
Result	✓ Passed
Next expiry date	2024-07-05

MOT #12	2022-07-06 14:43
MOT test number	160130929799
Result	✓ Passed

MOT #11	2021-06-23 09:46
MOT test number	990824005649
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2020-07-06 15:05
MOT test number	889439152508
Result	✓ Passed

CarCheck.co.uk page 3/12



DK10UAS

report date: 2024-03-28

MOT test number

Result

Advice Exhaust has a minor leak of exhaust gases flexi section (6.1.2 (a))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8 2018-03-28 10:44 **MOT** test number 581011166863 Result ✓ Passed **MOT #7** 2018-03-28 10:44 **MOT** test number 672929221574 Result × Failed Pass with rectification Front registration plate faded (6.3.1d) Pass with rectification Rear registration plate faded (6.3.1d)

MOT test number
959598175826

Result

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened and o/s/f (3.5.1i)

Advice Nearside Rear and o/s/r parking brake travel too high need adjusting

Advice Nearside Front Brake pad(s) wearing thin and o/s/f (3.5.1g)

CarCheck.co.uk page 4/12



DK10UAS

report date: 2024-03-28

MOT #5		2016-01-28 11:38
MOT test	number	313215507005
Result		X Failed
Advice	Nearside Front brake disc worn, pit	itted or scored, but not seriously weakened and o/s/f (3.5.1i)
Advice Nearside Front Brake pad(s) wearing thin and o/s/f (3.5.1g)		
Advice Nearside Rear and o/s/r parking brake travel too high need adjusting		
Pass wit	h rectification Nearside Front He	Headlamp aim too low and too far to the left. and o/s/f (1.8)

MOT #4		2015-02-21 11:45
MOT test number		845662255054
Result		✓ Passed
MOT #3		2014-03-15 10:08
MOT test number		729634074059
Result		✓ Passed
MOT #2		2014-03-15 10:08
MOT test number		256104774026
Result		× Failed
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)	

MOT #1	2013-02-19 17:02
MOT test number	546970053076
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	AIR UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-03-18
Last registration	2023-07-03
Complete history	See info



Registration #1	2010-03-18	16 mi
Registration #2	2013-02-19	49.635 mi
Registration #3	2014-03-15	54.791 mi
Registration #4	2015-02-21	61.551 mi
Registration #5	2016-01-28	69.292 mi
Registration #6	2016-01-28	69.292 mi
Registration #7	2018-03-28	89.063 mi
Registration #8		7.77
Registration #9		77.777 46
Registration #10		7.77
Registration #11		0.074
Registration #12		77.777 46
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	3
	70/70

CarCheck.co.uk page 12/12

Number of seats	5
Engine number	CGP0208149