



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-07-02
Pictures	40
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-01
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	5

MOT #12	2024-02-27 11:07
MOT test number	752756797647
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Minor	Front Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))

MOT #11	2024-02-26 16:07
MOT test number	302960865120
Result	✗ Failed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Minor	Front Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**MOT #10** 2023-03-01 12:47**MOT test number** 468436034648**Result** ✓ Passed

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**MOT #9** 2023-03-01 12:47**MOT test number** 727916005168**Result** ✗ Failed

**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))

**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))

**MOT #8** 2021-12-09 15:26**MOT test number** 580122946407**Result** ✓ Passed

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Rear Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))

**MOT #7** 2020-11-04 09:04**MOT test number** 344587511899**Result** ✓ Passed**MOT #6** 2019-05-31 09:45**MOT test number** 348981103320**Result** ✓ Passed**MOT #5** 2018-06-16 10:01**MOT test number** 710931732601**Result** ✓ Passed



MOT #4	2017-06-10 09:27
MOT test number	547540769959
Result	✓ Passed
MOT #3	2016-06-08 13:53
MOT test number	895104746165
Result	✓ Passed
MOT #2	2015-06-16 15:13
MOT test number	216047165484
Result	✓ Passed
MOT #1	2014-06-23 11:50
MOT test number	557124974170
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	3
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LV110XH</b>
Plate since	2019-06-29
Current registration	<b>LV110XH</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-05-20
Last registration	2024-02-27
Complete history	<a href="#">See info</a>



Registration #1	2011-05-20	15 mi
Registration #2	2014-06-23	16.075 mi
Registration #3	2015-06-16	23.601 mi
Registration #4	2016-06-08	29.324 mi
Registration #5	2017-06-10	36.492 mi
Registration #6	2018-06-16	43.817 mi
Registration #7	2019-05-31	58.887 mi
Registration #8	2020-05-20	59.277 mi
Registration #9	2020-05-20	59.277 mi
Registration #10	2020-05-20	59.277 mi
Registration #11	2020-05-20	59.277 mi
Registration #12	2020-05-20	59.277 mi
Registration #13	2020-05-20	59.277 mi
Registration #14	2020-05-20	59.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Number of axles**

2

**Engine number**

CAY 586764