



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 R-LINE TECH TDI
Colour	Grey
Year of manufacture	2019
Top speed	146 mph
0 - 100 km/h	6.1 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	210 kW / 286 HP / 282 BHP
Max. torque	600 Nm at 2.250 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	30.5 mpg
Consumption extra urban	39.9 mpg
Consumption combined	34.0 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-05-19
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-27
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #4 2024-03-28 08:08

MOT test number 752176006712

Result ✓ Passed

Next expiry date 2025-03-27

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear arm inner bush (5.3.4 (a) (i))

MOT #3 2024-03-13 17:24

MOT test number 179929950939

Result ✗ Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement rear arm, inner bush (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear inner bush (5.3.4 (a) (i))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear inner bush (5.3.4 (a) (i))

MOT #2 2023-03-17 10:44

MOT test number 424353093373

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #1	2022-03-23 14:24
MOT test number	299968105856
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 March 2025

Tax status	Valid until 1 November
Days left	185
MOT expiry date	27 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KP19JXT
Plate since	2019-03-29
Current registration	 KP19JXT
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-03-26
Last registration	2024-03-28
Complete history	See info



Registration #1	2019-03-26	18 mi
Registration #2	2022-03-23	26.059 mi
Registration #3	2023-03-23	26.059 mi
Registration #4	2023-03-23	26.059 mi
Registration #5	2023-03-23	26.059 mi
Registration #6	2024-03-28	26.059 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	86%
Pedestrian	72%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1984 mm
Height	1702 mm
Length	4878 mm
Wheel base	2904 mm
Kerb weight	1970 kg

Additional information

Fuel tank capacity	75 l
Number of axles	2
Engine number	DENA021968