





report date: 2024-03-29

General information

Make	FIAT
Model	SEDICI 16V ELEGANZA
Colour	Grey
Year of manufacture	2006
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	173 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-07-23

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-21

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-16
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #16		2023-08-14 14:49
MOT test	number	693400331092
Result		✓ Passed
Next expi	ry date	2024-08-16
Advice	Rear Passenger seat(s) missing at time of test	
Advice	Nearside Front Passenger seat(s) missing at time of test	

MOT #15		2022-08-12 15:53
MOT test	number	627323687866
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2021-08-17 16:17
MOT test number	346547485884
Result	✓ Passed

CarCheck.co.uk page 3/13



Minor

WN56JHF

report date: 2024-03-29

MOT test number

Result

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Central Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12

MOT test number

625800360730

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

MOT test number

Result

MOT #10

2019-02-26 14:02

798208376367

✓ Passed

MOT test number

925521475389

Result

✓ Passed

MOT #9

MOT test number

691373103148

Result

Advice Front pads getting low

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/13



MOT #8

Result

WN56JHF

report date: 2024-03-29

2016-02-02 14:16

✓ Passed

MOT test number	151611394267
Result	✓ Passed
MOT #7	2016-01-28 11:53
MOT test number	882463289976
Result	≍ Failed
Fail Offside Front coil spring broken (2.4.C.1a)	
MOT #6	2015-02-03 11:07
MOT test number	797734135048
Result	✓ Passed
MOT #5	2014-01-31 14:48
MOT test number	957871934083
Result	✓ Passed
Notice All tyres cracking in treads	

MOT #4	2013-02-11 10:26
MOT test number	259292243071
Result	✓ Passed
MOT #3	2012-01-28 09:26
MOT test number	579488422085

MOT #2	2011-01-19 15:22
MOT test number	687799511078
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #1 2010-02-02 16:35

MOT test number 960083630041

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



WN56JHF

report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when mistery	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
STATE OF THE PARTY	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



WN56JHF

report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-31
Last registration	2023-08-14
Complete history	See info



Registration #1	2006-10-31	13 mi
Registration #2	2010-02-02	13.537 mi
Registration #3	2011-01-19	15.667 mi
Registration #4	2012-01-28	17.467 mi
Registration #5	2013-02-11	19.018 mi
Registration #6	2014-01-31	20.681 mi
Registration #7	2015-02-03	22.223 mi
Registration #8	2016-01-28	23.608 mi
Registration #9	2016-02-02	23.628 mi
Registration #10	2017-02-08	25.182 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		71,777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	*****
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1620 mm
Length	4115 mm
Wheel base	2500 mm
Kerb weight	1195 kg
Max. allowed weight	2870 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1.

Number of axles2Engine number1173775