



PF63JKU


report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	White
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2024-12-19
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	15
Total items failed	5

MOT #12 2023-12-14 13:21

MOT test number 570035602325

Result ✓ Passed

Next expiry date 2024-12-19

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm & outer edge badly worn (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm& outer edge badly worn (5.2.3 (e))

MOT #11 2023-12-14 13:21

MOT test number 351799917902

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm & outer edge badly worn (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm& outer edge badly worn (5.2.3 (e))

**MOT #10** 2022-12-20 10:21**MOT test number** 536179590508**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged inner wall (5.2.3 (d) (ii))**MOT #9** 2021-11-17 16:43**MOT test number** 733301958265**Result** ✓ Passed**Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2020-12-08 12:19**MOT test number** 150481884032**Result** ✓ Passed**MOT #7** 2019-12-17 14:06**MOT test number** 988418940951**Result** ✓ Passed**MOT #6** 2019-12-14 10:06**MOT test number** 225765596096**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-12-13 09:32**MOT test number** 205641803311**Result** ✓ Passed**MOT #4** 2018-12-13 09:32**MOT test number** 555708700908**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #3** 2017-12-16 09:48**MOT test number** 449524471464**Result** ✓ Passed**MOT #2** 2016-12-15 12:48**MOT test number** 761118525925**Result** ✓ Passed**MOT #1** 2016-12-15 09:24**MOT test number** 549482966454**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
19 December 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-31
Last registration	2023-12-14
Complete history	See info



Registration #1	2013-12-31	10 mi
Registration #2	2016-12-15	10.650 mi
Registration #3	2016-12-15	10.650 mi
Registration #4	2017-12-16	14.816 mi
Registration #5	2018-12-13	18.422 mi
Registration #6	2018-12-13	18.422 mi
Registration #7	2019-12-14	21.743 mi
Registration #8	2019-12-14	21.743 mi
Registration #9	2019-12-14	21.743 mi
Registration #10	2019-12-14	21.743 mi
Registration #11	2019-12-14	21.743 mi
Registration #12	2019-12-14	21.743 mi
Registration #13	2019-12-14	21.743 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1640153