



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT-R AWD
Colour	Grey
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-11-24
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-31
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-24
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	14
Total items failed	2

MOT #14 2023-10-05 13:42

MOT test number 976027338212

Result ✓ Passed

Next expiry date 2024-10-24

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2022-10-25 14:02

MOT test number 634679791244

Result ✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2022-10-25 11:10

MOT test number 311333903532

Result ✗ Failed

**MAJOR** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2021-08-31 16:22**MOT test number** 575268366110**Result** ✓ Passed**Advice** Surface corrosion and wax oil/underseal underside**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside rear shock absorber case corroded**Advice** Brake pipe corroded, covered in grease or other material Several brake pipes covered in wax oil/underseal (1.1.11 (c))**MOT #10** 2021-08-27 15:08**MOT test number** 112279942748**Result** ✗ Failed**Advice** Surface corrosion and wax oil/underseal underside**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Offside rear shock absorber case corroded**Advice** Brake pipe corroded, covered in grease or other material Several brake pipes covered in wax oil/underseal (1.1.11 (c))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9** 2020-09-14 09:22**MOT test number** 286353783870**Result** ✓ Passed**MOT #8** 2019-10-03 09:06**MOT test number** 781879458597**Result** ✓ Passed**MOT #7** 2018-10-01 08:39**MOT test number** 126617266207**Result** ✓ Passed



<b>MOT #6</b>	2017-09-28 08:58
---------------	------------------

<b>MOT test number</b>	597940458355
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2016-09-15 09:02
---------------	------------------

<b>MOT test number</b>	268269998087
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2015-10-14 08:34
---------------	------------------

<b>MOT test number</b>	176858700048
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-10-14 08:34
---------------	------------------

<b>MOT test number</b>	694716349434
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

<b>Pass with rectification</b>	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	---

<b>MOT #2</b>	2015-07-10 13:06
---------------	------------------

<b>MOT test number</b>	136721695141
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2014-07-25 09:06
---------------	------------------

<b>MOT test number</b>	758156204260
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-01
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2011-09-01	10 mi
Registration #2	2014-07-25	35.483 mi
Registration #3	2015-07-10	43.429 mi
Registration #4	2015-10-14	45.221 mi
Registration #5	2015-10-14	45.221 mi
Registration #6	2016-09-15	56.072 mi
Registration #7	2017-09-28	66.522 mi
Registration #8	2018-10-01	76.848 mi
Registration #9	2019-10-03	80.365 mi
Registration #10	2020-05-20	85.377 mi
Registration #11	2020-05-20	85.377 mi
Registration #12	2020-05-20	85.377 mi
Registration #13	2020-05-20	85.377 mi
Registration #14	2020-05-20	85.377 mi
Registration #15	2020-05-20	85.377 mi
Registration #16	2020-05-20	85.377 mi
Registration #17	2020-05-20	85.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4365 mm
Wheel base	2560 mm
Kerb weight	1650 kg
Max. allowed weight	2190 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

2AD0355304