



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO TWINAIR
Colour	White
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 2.000 rpm
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-21
Pictures	28
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #9 2022-08-23 08:14

MOT test number 226843279966

Result ✓ Passed

Next expiry date 2023-08-22

- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively both NS and OS (1.1.14 (a) (i))
- Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Brake pad warning wire snapped OSF.
- Advice** Tyre slightly damaged/cracking or perishing all four tyres (5.2.3 (d) (ii))
- Advice** Nearside Non obligatory mirror damaged Glass missing

**MOT #8**

2022-08-01 13:55

MOT test number

411772898041

Result**✗ Failed****Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Front Pad warning light wore snapped.**Fail** Offside Headlamp insecure (4.1.1 (c))**Fail** Engine mounting damaged or deteriorated resulting in excessive movement Gearbox/Engine bracket rear of gearbox. (6.1.8 (a) (i))**Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))**Fail** Emissions not tested Due to failure of the flexible exhaust section. (8.2.1.2 (d))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Wing mirror missing.**Advice** Tyre slightly damaged/cracking or perishing All four tyres. (5.2.3 (d) (ii))**Fail** Nearside Headlamp insecure (4.1.1 (c))**Fail** Offside Side repeater missing (4.4.1 (a) (ii))**Fail** Exhaust emissions likely to be affected by an exhaust leak Front flexible section damaged from the mounting broken. (8.2.1.1 (b))**Fail** Windscreen washer not working Both NS and OS (3.5 (a))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively Both NS and OS. (1.1.14 (a) (i))**MOT #7**

2021-07-12 16:47

MOT test number

995498386744

Result**✓ Passed**

**MOT #6** 2020-07-13 11:25**MOT test number** 112770585657**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Shock absorbers light misting of oil or has limited damping effect both side (5.3.2 (b))**MOT #5** 2019-08-15 10:18**MOT test number** 673489653658**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #4** 2018-08-15 07:32**MOT test number** 521093312662**Result** ✓ Passed**MOT #3** 2017-08-03 09:14**MOT test number** 609473472176**Result** ✓ Passed**MOT #2** 2016-08-03 14:55**MOT test number** 294239449929**Result** ✓ Passed**MOT #1** 2015-07-20 17:15**MOT test number** 299901005216**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2012-07-31
Last registration	2022-08-23
Complete history	See info



Registration #1	2012-07-31	10 mi
Registration #2	2015-07-20	26.546 mi
Registration #3	2016-08-03	35.169 mi
Registration #4	2017-08-03	42.233 mi
Registration #5	2018-08-15	46.820 mi
Registration #6	2019-08-15	49.700 mi
Registration #7	2020-08-23	51.277 mi
Registration #8	2021-08-23	51.277 mi
Registration #9	2022-08-23	51.277 mi
Registration #10	2023-08-23	51.277 mi
Registration #11	2024-03-28	51.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1075 kg
Max. allowed weight	1635 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

0075922